



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70833



Customer #: 23199
HOFFMAN, JOSEPH



CUSTOMER WORK ORDER

WO #: 70833

Customer: 23199 - HOFFMAN, JOSEPH -
812-604-1758

Tag:

Author: BH

Location: 0614 BH TO CHECK PREAUTH

Stock #: P4733

Stock Desc: 2022 5W KEYSTONE
COUGAR HALF-TON 32BHS

Chassis #: 4YDFCGR29N2504733

Serial #: 4YDFCGR29N2504733

Mileage:

Licence:

Invoice #:

Date In: 05 JUN 23

Promised:

Date Sched:

Completed: 14 JUN 23

Warr. Date: 14 JAN 23

Job #1 - Warranty

COMPLAINT: BLIND IN THE BUNKROOM FELL DOWN

CORRECTION: REINSTALLED VALANCE WITH EXTRA SCREWS.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	32.00
Subtotal for Job #1:			32.00

Job #2 - Internal

COMPLAINT: SHOWER IS LEAKING WHERE IT CONNECTS AT THE HOSE

CORRECTION: THE FITTING ON THE FAUCET SIDE OF HOSE WAS NOT INSTALLED STRAIT I TOOK OFF AND ALINGED THE THREADS AND TIGHTENED

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Subtotal for Job #2:			0.00

Job #3 - Warranty

SHOWER WALL PLUGS ARE COMING OU TOF THE WALL

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	48.00
Subtotal for Job #3:			48.00

Job #4 - Internal

COMPLAINT: LOOK AT DINNETTE TABLE IS GOES DOWN WHILE EATING AT THE TABLE

CORRECTION: THERE IS A MANUAL LOCK ON THE BOTTOM OF THE TABLE TO KEEP IT FROM GOING DOWN

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	N/C



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: BLIND IN THE BED ROOM HAS FELL DOWN TOO

CORRECTION: HAD TO ADJUST THE LATCH AND PUSHED HARD TO GET IT TO SNAP IN.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	32.00
Subtotal for Job #5:			32.00

Parts Total: 0.00
Labour Total: 112.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 112.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 14 Jun 2023

W/O: 70833



Customer #: 23199
HOFFMAN, JOSEPH

