

# e-Authorization

7/7/20  
05:13:53

3-Authorization number PA03475083 Reference no: 70856 Status: Approved Approved by Larry Approved date 7/6/2023  
 Naming Name Address VIN Retail sold on

| 34             | Basden's American RV | Basden's American RV<br>600 E Baseline Rd<br>Evansville, IN 47725 | 4YDFCGS23PF507634 |           |                |              |     |            |                                                                                                                                                                                                                                                                                                                                                                                                           |
|----------------|----------------------|-------------------------------------------------------------------|-------------------|-----------|----------------|--------------|-----|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Item           | Root of operation    | Description                                                       | Sublet            | Sub hours | Approved hours | Actual hours | Qty | Base hours | Complaint / Cause / Correction                                                                                                                                                                                                                                                                                                                                                                            |
| 1              | 3103714A             | Medicine Cabinet                                                  | 0.00              | 0.10      | 0.10           |              | 1   | 0.10       | Complaint:BATHROOM MED CABINET DOOR WONT SHUT<br>Cause:LATCH NEEDED ADJUSTED<br>Correction:ADJUSTED LATCH SO IT WOULD CATCH.                                                                                                                                                                                                                                                                              |
| KRV - Approved |                      |                                                                   |                   |           |                |              |     |            |                                                                                                                                                                                                                                                                                                                                                                                                           |
| 2              | 2202114A             | Grab Handle - Re                                                  | 0.00              | 0.20      | 0.20           |              | 1   | 0.20       | Complaint:HANDLE TO THE STAIRS IS LOOSE<br>Cause:TOOK HANDLE OFF AND TOOK OUT CONTROL PANEL TO LOOK IN WALL FOR STUD,FOUND STUD,THEY MISSED THE STUD WITH SCREWS,MOVED HANDLE AND SCREWED INTO STUDS.<br>Correction:TOOK HANDLE OFF AND TOOK OUT CONTROL PANEL TO LOOK IN WALL FOR STUD,FOUND STUD,THEY MISSED THE STUD WITH SCREWS,MOVED HANDLE AND SCREWED INTO STUDS.                                  |
| KRV - Approved |                      |                                                                   |                   |           |                |              |     |            |                                                                                                                                                                                                                                                                                                                                                                                                           |
| 3              | 3200114A             | Door - Interior Hin                                               | 0.00              | 0.20      | 0.20           |              | 1   | 0.20       | Complaint:BATHROOM DOOR IN BACK WONT SHUT<br>Cause:Took off top trim to get to top of door to adjust rollers, adjusted rollers on door to move, all good.<br>Correction:Took off top trim to get to top of door to adjust rollers, adjusted rollers on door to move, all good.                                                                                                                            |
| KRV - Approved |                      |                                                                   |                   |           |                |              |     |            |                                                                                                                                                                                                                                                                                                                                                                                                           |
| 4              | 6109414A             | Holding Tank Flus                                                 | 0.00              | 0.70      | 0.70           |              | 1   | 0.20       | Complaint:VACUUM BREAKER IS HOOKED UP BACKWORDS<br>Cause:HOOKED UP WATER TO FRONT BLACK TANK FLUSH AND NO WATER WILL COME THROUGH TRACED LINE TO VACUUM BREAKER AND FOUND IT WAS HOOKED BACKWARDS,HAD TO CUT THE ENDS OFF AND REINSTALL ON OPPOSITE LINE,ALSO FOUND VACUUM BREAKER WAS BROKEN,INSTALLED NEW VACUUM BREAKER AND 2 CONE WASHERS,ALL GOOD.<br>Correction:HOOKED UP WATER TO FRONT BLACK TANK |

paper claims only use one pre-authorization number per warranty claim for multiple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

