



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70856
Promised Date: 20 JUN 23

CUSTOMER WORK ORDER

WO #: 70856

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0705 BH TO CLOSE

Stock #: 10607
Stock Desc: 2023 5W KEYSTONE
COUGAR 364BHL
Chassis #: 4YDFCGS23PF507634
Serial #: 4YDFCGS23PF507634
Mileage:
Licence:

Invoice #:
Date In: 06 JUN 23
Promised: 30 JUN 23
Date Sched:
Completed: 30 JUN 23
Warr. Date:

Job #PDINFW - Internal

PDI - NEW FIFTH WHEEL

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: BATHROOM MED CABINET DOOR WONT SHUT

CORRECTION: ADJUSTED LATCH SO IT WOULD CATCH.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	16.00

Subtotal for Job #1: 16.00

Job #2 - Warranty

COMPLAINT: HANDLE TO THE STAIRS IS LOOSE

CORRECTION: TOOK HANDLE OFF AND TOOK OUT CONTROL PANEL TO LOOK IN WALL FOR STUD,FOUND STUD,THEY MISSED THE STUD WITH SCREWS,MOVED HANDLE AND SCREWED INTO STUDS.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	32.00

Subtotal for Job #2: 32.00

Job #3 - Warranty

COMPLAINT: BATHROOM DOOR IN BACK WONT SHUT

CAUSE: Took off top trim to get to top of door to adjust rollers,adjusted rollers on door to move,all good.

Labor



Customer #: 1000
BASDEN'S AMERICAN RV,



Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	32.00

Subtotal for Job #3: 32.00

Job #4 - Warranty

COMPLAINT: VACUUM BREAKER IS HOOKED UP BACKWORDS

CAUSE:

CORRECTION: HOOKED UP WATER TO FRONT BLACK TANK FLUSH AND NO WATER WILL COME THROUGH TRACED LINE TO VACUUM BREAKER AND FOUND IT WAS HOOKED BACKWARDS, HAD TO CUT THE ENDS OFF AND REINSTALL ON OPPISITE LINE, ALSO FOUND VACUUM BREAKER WAS BROKEN, INSTALLED NEW VACUUM BREAKER AND 2 CONE WASHERS, ALL GOOD.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	112.00

Parts

Part #	Description	Qty	Price	Total
282770	94239 VACUUM BREAKER/CHECK VALVE	2.00	19.67	39.34
10-7150	CONE WASHER SWIVEL SEAL	2.00	0.18	0.36

Subtotal for Job #4: 151.70

Job #5 - Warranty

COMPLAINT: TRIM LOOSE IN BACK BATHROOM DOOR

CAUSE: Trim loose

CORRECTION: Staped trim back in place.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	16.00

Subtotal for Job #5: 16.00

Parts Total:	39.70
Labour Total:	208.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	247.70

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 07 Jul 2023

W/O: 70856
Promised Date: 30 JUN 23



Customer #: 1000
BASDEN'S AMERICAN RV,

