



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70866



CUSTOMER WORK ORDER

WO #: 70866

Customer: 53694 - GODSEY, JAY -
812-480-3480

Tag:

Author: BJW

Location: 0612 CHECK PREAUTH

Stock #: 10916

Stock Desc: 2022 TT FOREST RIVER
CHEROKEE 274BRB

Chassis #: 4X4TCKC25NX158985

Serial #: 4X4TCKC25NX158985

Mileage:

Licence:

Invoice #:

Date In: 07 JUN 23

Promised:

Date Sched:

Completed: 09 JUN 23

Warr. Date: 31 MAY 23

Job #1 - Warranty

COMPLAINT: AC UNIT INSIDE PLENUM BOWING DOWN INSIDE

CAUSE: AC UNIT INSIDE PLENUM BLOWING DOWN INSIDE.

CORRECTION: Removed ceiling plenum. Found that inside plenum was mounted with wrong side down. This allowed air return divider to shift and cause discharge and return air to mix. Both ceiling plenums are broken. Also ducts need to be retaped to seal properly. Retaped around ducts. Installed new inside and ceiling plenum.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	120.00

Parts

Part #	Description	Qty	Price	Total
41-0098	Air Conditioner Ceiling Assembly; DE	1.00	79.68	79.68

Subtotal for Job #1: 199.68

Parts Total: 79.68
Labour Total: 120.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 199.68

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 09 Jun 2023

Customer #: 53694
GODSEY, JAY

