

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 70939  
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO  
Customer: 4498 - KELLI J. HUFF  
Address: 200 S CHARLES ST WEST SALEM, IL

62476

Phone: 618-302-3521

Stock Number: 10969 - 2023 COUGAR HALF-TON 22RBS 4YDTCGK22PV501638

VIN: 4YDTCGK22PV501638 HIN: SER#: 4YDTCGK22PV501638

Mileage: 0 Work Order Comp: 30 JUN 23

Auth. No: Dealer #: 1194

Warr. Date: 17 JUN 23 Work Order Date: 15 JUN 23 Inv #: 393340

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*  
70939 8 THE RADIO/DVD PLAYER IS NOT WORKING TO THE TV  
No HDMI signal output on DVD radio AV output is ok  
Pull radio from cabinet and check wires get test TV and connect  
to radio and test no HDMI output test AV output have signal, Pull  
HDMI cables out and run AV cables in place of HDMI wire up to TV  
and test  
  
70939 3 TRIM STRIP ON THE SLIDE ROOM IS LOOSE  
Nai in place  
  
70939 4 BATHROOM DOOR NOT LATCHING  
Door frame to wide  
Remove latch side of door frame and install shims behind door  
frame install door frame and latch test door  
  
70939 5 WATER RUNNING OUT OF THE UNDER BELLY WHEN USING THE BLACK TANK  
FLUSH  
Loose fittings  
Open access panel and found fittings leaking, tighten fittings  
and test  
  
70939 7 THE BOTTOM OF THE BED BASE THE BOARDS ARE LOOSE  
Staple board back in place

\*\*\*\*\*  
Part No Job# Description PARTS Qty Price Total  
\*\*\*\*\*  
3183357 8 AUD/VID RCA 6' 1.00 16.09 16.09

Claim : 70939

\*\*\*\*\*  
 Part No      Job#    Description      PARTS                   Qty      Price      Total  
 \*\*\*\*\*

\*\*\*\*\*  
 Lab Code   Job#    Description      LABOUR                   Hrs      Rate      Total  
 \*\*\*\*\*  
 Z990           8    MISCELLANEOUS REPAIR                   0.00    160.00      0.00  
 Z990           8    MISCELLANEOUS REPAIR                   0.30    160.00     48.00  
 Z990           3    MISCELLANEOUS REPAIR                   0.00    160.00      0.00  
 Z990           3    MISCELLANEOUS REPAIR                   0.10    160.00     16.00  
 Z990           4    MISCELLANEOUS REPAIR                   0.70    160.00    112.00  
 Z990           5    MISCELLANEOUS REPAIR                   0.20    160.00     32.00  
 Z990           7    MISCELLANEOUS REPAIR                   0.00    160.00      0.00  
 Z990           7    MISCELLANEOUS REPAIR                   0.20    160.00     32.00

Parts Total:           16.09  
 Labour Total:          240.00  
 Sublet Total:           0.00  
 Extras Total:           0.00

>>>> Claim Total:       256.09

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_