



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71040
Promised Date:
06/11/23



Customer #: 28601
GRIEPENSTROH, BRAD A.



CUSTOMER WORK ORDER

WO #: 71040 (Appointment Date: 27 JUN 2023 - Time: 03:00pm)

Customer: 28601 - GRIEPENSTROH,
BRAD A. - 812-202-0474

Tag:

Author: PH

Location: 0801 CHECK WOR

Stock #: 10820

Stock Desc: 2022 TT FOREST RIVER
CHEROKEE 264DBH

Chassis #: 4X4TCKB27NX156687

Serial #: 4X4TCKB27NX156687

Mileage: 0

Licence:

Invoice #:

Date In: 20 JUN 23

Promised: 29 JUL 23

Date Sched:

Completed: 27 JUL 23

Warr. Date: 27 JUN 22

Job #1 - Internal

COMPLAINT: SLIDE OUT KEEPS BLOWING FUSES. NOT ALWAYS, IS INTERMITTANT

CORRECTION: i have ran room inand out 4 Or 5 times and cannot get it to blow any fuses.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: ENTRY DOORS (BOTH) ARE NOT SHUTTING PROPERLY, BOTH NEED ADJUSTED

CAUSE: .

CORRECTION: ADJUSTED BOTH ENTRY DOOR CATCHES BOTH DENNY AND I THOUGHT THEY CLOSED GOOD NOW.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	96.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00

Subtotal for Job #2: 96.00

Job #3 - Warranty

COMPLAINT: ALL 3 OUTSIDE COMPARTMENT DOORS ARE HARD TO CLOSE AND LOCK

CAUSE: i found that the compartment doors are very difficult the front door is bowed and in need of replacement. the rear door seems to have adjusted and is working .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	80.00

Parts

Part #	Description	Qty	Price	Total
5952	15.75 X 27.75 COMP DOOR - BLACK	1.00	31.97	31.97



W/O: 71040
Promised Date: 29 JUL 23



Customer #: 28601
GRIEPENSTROH, BRAD A.



Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	42.38	42.38

Subtotal for Job #3: 154.35

Job #4 - Warranty

COMPLAINT: INTERIOR PANTRY DOOR IS MISALIGNED AND NOT SHUTTING PROPERLY

CORRECTION: there was wood holding the frame out at the top and the hinge was bent i took hinge off and bent strait and sanded off the exces wood now it closes good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	32.00

Subtotal for Job #4: 32.00

Job #5 - Warranty

COMPLAINT: CABINET OVER BED NOT STAYING CLOSED, IT KEEPS FALLING OPEN

CORRECTION: striker was too high i moved it down so it would latch.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	16.00

Subtotal for Job #5: 16.00

Job #6 - Internal

COMPLAINT: DOOR SIDE GUTTER IS LEAKING AT THE JOINT

CORRECTION: sealed the seam on the gutter and sealed the top edge of the gutter

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

Subtotal for Job #6: 0.00

Parts Total: 31.97
Labour Total: 224.00
Sublet Total: 0.00
Extras Total: 42.38
WORK ORDER TOTAL: 298.35

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Jul 2023

