

e-Authorization

7/10/20
09:14:24

3-Authorization number PA03478665 Reference no: 71086 Status: Approved Approved by hull Approved date 7/7/2023
Billing Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTCGK26NL509797 4/1/2023
600 E Baseline Rd
Evansville, IN 47725

Job Root Description of operation	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1 6104415A Shower/Tub - Doc	0.00	2.50	2.00		1	0.50	Complaint: CUSTOMER ADVISES THAT BOTTOM TRACK FOR THE SHOWER DOORS IS ON BACKWARDS. IT HAS THE DRAIN HOLES GOING TO THE OUTSIDE. CUSTOMER ADVISES THAT IT IS CUT TO SHORT AS WELL Cause: SHOWER PUT TOGETHER WRONG, RAIL DRAINS TO OUTSIDE SHOWER Correction: FIND AND BRING IN UNIT OFF OF LOT, REMOVE SHOWER DOORS, REMOVE DOOR FRAMES, CLEAN OFF OLD SEALER, INSTALL DOOR FRAME, INSTALL DOORS, CAP SEAL AROUND DOOR FRAME, CLOSE UP UNIT AND PUT OUT ON LOT

KRV - Labor time approved and adjusted in accordance with
Keystone RV's flat rate manual.

3-Authorization number PA03478665

2.00

paper claims only use one pre-authorization number per warranty claim for
multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the