



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71104
Promised Date:
20 11 11 22

CUSTOMER WORK ORDER

WO #: 71104

Customer: 44932 - SUTTON, DENNIS A.
- 812-646-1059

Tag:

Author: BJW

Location: 0724 SEE IF BEN HAS
CALLED THIS IN TO SERVICE
CONTRACT YET

Stock #: 10943

Stock Desc: 2022 TT COACHMEN
CATALINA 303RKDSLE

Chassis #: 5ZT2CAVB3NX024693

Serial #: 5ZT2CAVB3NX024693

Mileage: 0

Licence:

Invoice #:

Date In: 06 JUL 23

Promised: 29 JUL 23

Date Sched:

Completed: 24 JUL 23

Warr. Date: 19 MAY 22

Job #1 - Warranty

COMPLAINT: THE AWNING LIGHTS WILL NOT COME ON WITH THE INTERIOR SWITCH OR THE REMOTE.

CAUSE: Lights are inop. Swapped sensor and lights still inop.

CORRECTION: removed old awning light strip and installed new awning lights. plugged lights into LED harnis and the lights still did not work. i checked for a blown fuse and the fuse was good i removed the control panel and checked for power going into and out of the switch and i had power. i got with bill to help me figure out the issue we pulled the wires out of the bottom of the awning arm to see if something had come undone eeverything looked good we checked for power and ground and it was good. we decided to replace the LED control harnis and fixed the problem. i nstalled the new harnis and customer has a new remote also.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	80.00

Parts

Part #	Description	Qty	Price	Total
F100247635	LED LIGHTS FOR CAREFREE AWNING- FOR	1.00	137.91	137.91
F100207754	KIT, LED CONTROLLER/REMOTE	1.00	20.72	20.72

Subtotal for Job #1: 238.63

Parts Total: 158.63
Labour Total: 80.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 238.63

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer #: 44932
SUTTON, DENNIS A.