



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71120
Promised Date:
12 JUL 23

CUSTOMER WORK ORDER

WO #: 71120

Customer: 53835 - ROBLING, DALE L. -
812-484-7796

Tag:

Author: DH

Location: 0724 BH TO CLOSE

Stock #: 10767

Stock Desc: 2023 TT COACHMEN

CATALINA SUMMIT SERIES 164BHX

Chassis #: 5ZT2CAEC5PK006057

Serial #: 5ZT2CAEC5PK006057

Mileage:

Licence:

Invoice #:

Date In: 10 JUL 23

Promised: 13 JUL 23

Date Sched:

Completed: 24 JUL 23

Warr. Date: 13 JUL 23

Job #SUMMERLAND - Internal

SUMMERLAND PDI

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	4.00	N/C	N/C

Subtotal for Job #SUMMERLAND: 0.00

Job #SWAP - Internal

SWAP CUSTOMER'S HITCHWORK

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #SWAP: 0.00

Job #1 - Warranty

COMPLAINT: WHEN HOOKED TO CITY WATER, NO WATER REACHES THE FAUCETS.

CAUSE: No water

CORRECTION: took off city connection and found hose was twisted when put in, turned and untwisted and put back together.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	48.00

Customer #: 53835
ROBLING, DALE L.



Subtotal for Job #1: 48.00

Job #2 - Internal

COMPLAINT: LIGHTS DO NOT WORK ON THE STOVE

CAUSE: Light

CORRECTION: Took cover off of stove and found connection was loose on switch, installed cover back in place.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THE WATER HEATER IS LEAKING SEVERELY

CAUSE: water leak

CORRECTION: noticed water coming from front of water heater, under starfoam, took outer ring off outside and undid lp line, unhooked wires from inside and took off water lines, drained water tank, slide water tank out and pulled off styrofoam from tank, filled tank and found top fitting was leaking in behind styrofoam, and to front of bottom of tank, took out fitting and put sealant on it and installed back in place, put styrofoam back around tank and secured, slide tank back in hole and secured outside ring and sealed, went inside and hooked up 12 volt wires and hooked up water lines, filled with water and tested, no more leaks.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	240.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Subtotal for Job #3: 240.00

Parts Total:	0.00
Labour Total:	288.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	288.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 24 Jul 2023

W/O: 71120
Promised Date: 13 JUL 23

Customer #: 53835
ROBLING, DALE L.

