

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71137
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 53772 - CRYSTAL SPEGAL
Address: 1024 VANDERBURGH AVE
EVANSVILLE, IN
47711
Phone: (812) 457-0820
Stock Number: 2023 ZINGER

VIN: HIN: SER#: 4YDTZRR27PS370286
Mileage: Work Order Comp: 18 JUL 23
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 11 JUL 23 Inv #: 394283

JOB INFORMATION

WO #	Job #	Description
71137	1	THERE IS NO POWER AT ALL TO THE FRONT LEVELING JACKS AND REAR WON'T LIFT BUT WILL RETRACT Faulty circuit breaker Ran a test wire to jump the circuit breaker. Jack's worked while jumping the circuit breaker. Check continuity on Circuit breaker and would not work. Is circuit breaker was a six amp. Put in a thirty amp circuit breaker. CHECKED REAR JACKS COULD NOT RECREATE PROBLEM ON REAR JACKS. REAR JACKS WENT UP AND DOWN NO PROBLEMS.
71137	4	THE SHOWER LEAKS ALL AROUND WHERE THE DOOR MEETS THE BOTTOM OF THE SHOWER PAN. Shower glass to floor pan not properly sealed. When water is being sprayed on glass, water comes out the bottom of the glass and trim and onto the floor. Cleaned Around the glass and then silicone. Will let silicone dry water test later. After an hour checked the shower pan after being siliconed. Sprayed water along the glass and bottom. No water ran out onto the floor.
71137	3	THE INTERIOR WALL PANEL ON THE OFF DOOR SIDE OF THE BEDROOM IS BULGING OUT. Not enough staples to hold panel to stud. Stapled panel back to stud. Put more Staples in the panel than factory did. Taped the wall panel with wall tape.
71137	5	SLIDING DOOR CAME OFF HINGE

Claim : 71137

WO # Job # Description JOB INFORMATION

Sliding HINGE pulled away from door
Pull-down trim above door. Unclipped the other half of the door
from the hinge. Unclip the other Hinge that was not attached to
the door.. The skirt hangs back to door then stuck door back up
and track, followed by the trim. Door slides with ease. Took
pictures.

Part No	Job#	Description	PARTS	Qty	Price	Total
19-1441	1	16-3030	30A CIRCUIT BREAKER	1.00	3.82	3.82
13-1350	4	CLEAR	SIKASIL PLUS	1.00	16.59	16.59

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISCELLANEOUS	REPAIR	0.30	160.00	48.00
Z990	4	MISCELLANEOUS	REPAIR	0.00	160.00	0.00
Z990	4	MISCELLANEOUS	REPAIR	0.50	160.00	80.00
Z990	3	MISCELLANEOUS	REPAIR	0.00	160.00	0.00
Z990	3	MISCELLANEOUS	REPAIR	0.20	160.00	32.00
Z990	5	MISCELLANEOUS	REPAIR	0.00	160.00	0.00
				0.20	160.00	32.00

Parts Total: 20.41
Labour Total: 192.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 212.41

Customer Signature: _____

Date: _____