

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71172
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 53770 - STANLEY D. KUJAWA, JR.
Address: 2259 VOGEL RD EVANSVILLE, IN

47711

Phone: 812-453-6899

Stock Number: 11261 - 2023 SPRINGDALE 1860SS 4YDTSGH10PW102691

VIN: 4YDTSGH10PW102691 HIN: SER#: 4YDTSGH10PW102691

Mileage: 0 Work Order Comp: 24 JUL 23

Auth. No: Dealer #: 1194

Warr. Date: 23 JUN 23 Work Order Date: 15 JUL 23 Inv #: 394310

WO # Job # Description JOB INFORMATION

71172 2 THERE IS A WIRE THAT WAS LOOSE IN THE HITCH AREA THAT WAS LOOSE.
CUSTOMER DID A TEMPORARY REPAIR, BUT IT NEEDS TO BE REPAIRED
PROPERLY.
I CUT THE ZIP TIE THAT WAS MAKING THE WIRE TIGHT. I CUT OUT THE
SPLICE, ADDED SOME EXTRA LENGTH AND REWIRED IT USING HEAT SHRINK
WEATHER CONNECTORS

71172 3 THERE IS NO SUPPORT IN THE WALL FOR THE TV. THERE IS A STICKER
INDICATING THAT THERE IS A SUPPORT IN THE WALL, BUT CUSTOMER
CAN NOT FIND IT.
LOCATED WALL STUD TO MOUNT TV BRACKET. USED TEMPLATE TO LOCATE
POSITION OF BRACKET. INSTALLED TV MOUNTING PLATE TO BACK OF TV.
MOUNTED THE FULL MOTION BRACKET TO THE WALL. HUNG TV ON BRACKET
TIGHTENED UP SAFETY MOUNT SCREW ON BACK OF TV. I MADE A COAX
CABLE. HOOKED UP TV AND RAN A CHANNEL SEARCH IT PICKED UP 15
DIGITAL CHANNELS.

71172 4 THERE IS A PANEL BY THE DINING TABLE THAT IS LOOSE AND NEEDS TO
BE REAPPLIED PROPERLY.
STAPLED PANEL BACK AND FILLED NAIL HOLES WITH WOOD PUTTY

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISCELLANEOUS REPAIR 0.00 160.00 0.00

Z990 2 MISCELLANEOUS REPAIR 0.20 160.00 32.00

Claim : 71172

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990        2  MISCELLANEOUS REPAIR      0.00    160.00      0.00
Z990        3  MISCELLANEOUS REPAIR      0.00    160.00      0.00
Z990        3  MISCELLANEOUS REPAIR      2.00    160.00    320.00
Z990        4  MISCELLANEOUS REPAIR      0.00    160.00      0.00
Z990        4  MISCELLANEOUS REPAIR      0.20    160.00     32.00

```

```

Parts Total:      0.00
Labour Total:    384.00
Sublet Total:      0.00
Extras Total:      0.00

```

```

>>>>> Claim Total:    384.00

```

Customer Signature: _____

Date: _____