



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71172

CUSTOMER WORK ORDER

WO #: 71172 (Appointment Date: 15 JUL 2023 - Time: 03:00pm)

Customer: 53770 - KUJAWA, JR.,
STANLEY D. - 812-453-6899

Tag:

Author: BH

Location: 0725 CHECK PREAUTH

Stock #: 11261

Stock Desc: 2023 TT KEYSTONE
SPRINGDALE 1860SS

Chassis #: 4YDTS GH10PW102691

Serial #: 4YDTS GH10PW102691

Mileage:

Licence:

Invoice #:

Date In: 15 JUL 23

Promised:

Date Sched:

Completed: 24 JUL 23

Warr. Date: 23 JUN 23

Job #1 - Internal

COMPLAINT: THE TRAILER IS SITTING NOSE LOW WHEN
HOOKED TO THE TOW VEHICLE. WE ARE TO
LOOK AT THIS WHEN CUSTOMER COMES TO PICK
UP.

CORRECTION: TOOK PICS OF JOBS2 3 AND 4
RESET HITCH ON SUV AND FOUND THAT THE HITCH WAS BENT. CUSTOMER IS NOW USING A
TRUCK AND I RESET THE HITCH FOR THE TRUCK.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THERE IS A WIRE THAT WAS LOOSE IN THE
HITCH AREA THAT WAS LOOSE. CUSTOMER DID
A TEMPORARY REPAIR, BUT IT NEEDS TO BE
REPAIRED PROPERLY.

CORRECTION: I CUT THE ZIP TIE THAT WAS MAKING THE WIRE TIGHT. I CUT OUT THE
SPLICE, ADDED SOME EXTRA LENGTH AND REWIRED IT USING HEAT SHRINK WEATHER
CONNECTORS

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	0.00
Z990	MISCELLANEOUS REPAIR	DWW	32.00
Z990	MISCELLANEOUS REPAIR	DWW	0.00

Subtotal for Job #2: 32.00

Job #3 - Warranty

COMPLAINT: THERE IS NO SUPPORT IN THE WALL FOR THE
TV. THERE IS A STICKER INDICATING THAT
THERE IS A SUPPORT IN THE WALL, BUT
CUSTOMER CAN NOT FIND IT.



Customer #: 53770
KUJAWA, JR., STANLEY D.



CORRECTION: LOCATED WALL STUD TO MOUNT TV BRACKET. USED TEMPLATE TO LOCATE POSITION OF BRACKET. INSTALLED TV MOUNTING PLATE TO BACK OF TV. MOUNTED THE FULL MOTION BRACKET TO THE WALL. HUNG TV ON BRACKET TIGHTENED UP SAFTY MOUNT SCREW ON BACK OF TV. I MADE A COAX CABLE. HOOKED UP TV AND RAN A CHANEL SEARCH IT PICKED UP 15 DIGITAL CHANELS.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	0.00
Z990	MISCELLANEOUS REPAIR	DWW	320.00

Subtotal for Job #3: 320.00

Job #4 - Warranty

COMPLAINT: THERE IS A PANEL BY THE DINING TABLE THAT IS LOOSE AND NEEDS TO BE REAPPLIED PROPERLY.

CORRECTION: STAPLED PANEL BACK AND FILLED NAIL HOLES WITH WOOD PUTTY

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	0.00
Z990	MISCELLANEOUS REPAIR	DWW	32.00

Subtotal for Job #4: 32.00

Parts Total: 0.00
Labour Total: 384.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 384.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 24 Jul 2023

Customer #: 53770
KUJAWA, JR., STANLEY D.

