



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71211



Customer #: 53856
PAYNE, LOGAN



CUSTOMER WORK ORDER

WO #: 71211

Customer: 53856 - PAYNE, LOGAN -

Tag:

Author: PH

Location: 0906 CHECK WORK

Stock #:

Stock Desc: 2023 TT FOREST RIVER
COACHMAN CATALINA 263BHSCK

Chassis #:

Serial #: 5ZT2CARB1PU040969

Mileage:

Licence:

Invoice #:

Date In: 20 JUL 23

Promised:

Date Sched:

Completed: 31 AUG 23

Warr. Date:

Job #1 - Warranty

COMPLAINT: BLACK TANK FLUSH CHECK VALVE LEAKING

CAUSE: Check valve

CORRECTION: Replace black tank flush valve.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	48.00

Parts

Part #	Description	Qty	Price	Total
10-0033	160-85-A-3P-A BLK CITY WATER W/PLAST	1.00	10.02	10.02

Subtotal for Job #1: 58.02

Job #2 - Internal

COMPLAINT: SOLAR PANEL NOT CHARGING, SHOWING ERROR CODE ON CHARGE CONTROLLER

CORRECTION: I FOUND THAT THE SOLAR CONTROLLER WAS SET FOR AN AGM BATTERY AND THE TRAILER HAS A WET TYPE BATTERY. I CHANGED THE SETTING AND STARTED TESTING THE SYSTEM AGAIN. AFTER LETTING UNIT SET ALL DAY IN THE SUN WITH LIGHTS ON, I TURNED OFF THE LIGHTS AND THE CHARGE CONTROLLER SHOWED FULL CHARGE. NO ERROR CODE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #2: 0.00

Parts Total:	10.02
Labour Total:	48.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	58.02

