

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71224
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 53271 - JOHN M. MARSHALL
Address: 8836 HIGHLAND LAKE DR GEORGETOWN, IN

47122

Phone: 859-494-3105

Stock Number: 11152 - 2023 COUGAR HALF-TON 30BHS 4YDTCGP26PV505507

VIN: 4YDTCGP26PV505507 HIN: SER#: 4YDTCGP26PV505507

Mileage: 0 Work Order Comp: 28 JUL 23

Auth. No: Dealer #: 1194

Warr. Date: 21 APR 23 Work Order Date: 22 JUL 23 Inv #: 394460

WO # Job # Description JOB INFORMATION

71224 2 BLACK TANK FLUSH IS INSTALLED BACKWARDS
NO WATER FLOW ON BLACK TANK FLUSHER
UNLOAD CABINET, REMOVE PANEL, CUT WIRE TYES REMOVE BACK FLOW VALVE
FOUND APART, BLOW AIR THROUGH LINES AND FOUND WATER LINES ARE
BACKWARDS, IN LINE ON OUT OF VALVE, CUT LINES RESET ENDS INSTALL
NEW BACK FLOW VALVE, TEST WITH WATER, PUT CABINET BACK TOGETHER,

71224 5 CHECK WATER PUMP....CUSTOMER SAYS THE WATER PUMP HAS GOTTEN
LOUDER SINCE THEY HAD IT.
Water pump is noisy
CHECK WATER pump found hose pinched, cut out pinched section and
remount line, test has less noise

Part No Job# Description PARTS Qty Price Total

THE94239 2 94239 VACUUM BREAKER/CHECK VALVE 1.00 19.67 19.67
ESC06435 2 CONE WASHER SWIVEL SEAL 2.00 0.18 0.36

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISCELLANEOUS REPAIR 0.40 160.00 64.00
Z990 5 MISCELLANEOUS REPAIR 0.40 160.00 64.00

Parts Total: 20.03
Labour Total: 128.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 148.03

Customer Signature: _____

Date: _____

Claim : 71224

```
*****
Lab Code  Job#  Description      LABOUR                      Hrs      Rate      Total
*****
```