

e-Authorization

7/28/20
09:56:08

3-Authorization number PA03494245 Reference no: 71224 Status: Approved Approved by fishe Approved date 7/27/2023
rving Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTG6P26PV505507 4/21/2023
600 E Baseline Rd
Evansville, IN 47725

Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6109414A Holding Tank Flus	0.00	0.40	0.40		1	0.20	Complaint:BLACK TANK FLUSH IS INSTALLED BACKWARDS Cause:NO WATER FLOW ON BLACK TANK FLUSHER Correction:UNLOAD CABINET, REMOVE PANEL, CUT WIRE TYES REMOVE BACK FLOW VALVE FOUND APART, BLOW AIR THROUGH LINES AND FOUND WATER LINES ARE BACKWARDS, IN LINE ON OUT OF VALVE, CUT LINES RESET ENDS INSTALL NEW BACK FLOW VALVE, TEST WITH WATER, PUT CABINET BACK TOGETHER,
2	6101314A Fresh Water Pres	0.00	0.80	0.40		1	0.10	Complaint:CHECK WATER PUMP....CUSTOMER SAYS THE WATER PUMP HAS GOTTEN LOUDER SINCE THEY HAD IT. Cause:Water pump is noisy Correction:CHECK WATER pump found hose pinched, cut out pinched section and remount line, test has less noise

3-Authorization number PA03494245 0.80

paper claims ~~only~~ use one pre-authorization number per warranty claim for
ple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the