



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71370



Customer #: 53405
SHAFFER, DEBB K.



CUSTOMER WORK ORDER

WO #: 71370 (Appointment Date: 07 AUG 2023 - Time: 08:30am)

Customer: 53405 - SHAFFER, DEBB K. - Stock #: 10834

931-273-3423

Tag:

Author: PH

Location: 0820 CHECK PARTS

Stock Desc: 2022 TT FOREST RIVER

CHEROKEE GREY WOLF 26MBRR

Chassis #: 4X4TCKB21NK082177

Serial #: 4X4TCKB21NK082177

Mileage: 0

Licence:

Invoice #:

Date In: 07 AUG 23

Promised:

Date Sched:

Completed: 16 AUG 23

Warr. Date: 04 MAR 23

Job #1 - Internal

COMPLAINT: CONTROL PANEL KEEPS BLOWING THE 15A FUSE. SEEMS TO BE SPARATIC, HAS DONE IT THE MOSTWHEN LEVELING

CAUSE: Plug unit into shore power. Monitor panel does not have any leveling controls on it. Went to jack and ran up and down several times. Ran through all functions on panel. Asked service writer for more information on the job. Couldn't get any more information than I had before. Ran through all functions again and couldn't replicate the issue.

CORRECTION: No correction at this time.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: WATER PUMP KEEPS LOSING PRESSURE AFTER RUNNING FOR A SHORT TIME. THIS IS ALSO SPARATIC

CAUSE: Ran pump for 10 minutes. Let pump sit with system pressurized during completion of other jobs. Never lost pressure

CORRECTION: No correction.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: TV ANTENNA IS NOT WORKING VERY WELL AND THEY ARE GETTING NO RADIO STATIONS

CAUSE: Had to locate customers TV remote. Ran channel scan. Picked up 13 channels. TV signal is clear.

CORRECTION: No correction at this time.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C



Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: BEDROOM WINDOW BLIND HAS A SHREDDED CORD ON IT. NOT WORKING PROPERLY AS WELL

CAUSE: Need to replace blind. Blind cord is damaged and blind won't move up or down.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
F100072751	SHADE, 32" X 24" PLEATED NIGHT SHADE	1.00	14.82	14.82

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SHADE	1.00	17.25	17.25

Subtotal for Job #4: 64.07

Job #5 - Internal

COMPLAINT: FRIDGE LATCH LETS THE DOOR OPEN SLIGHTLY WHILE TRAVELING

CAUSE: This is how the latch is designed. There isn't anyway to adjust or tighten the latch.

CORRECTION: No correction.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: GUTTER HAS A SEEM ON DOOR SIDE THAT IS LEAKING

CAUSE: .

CORRECTION: Sealed gutter seam with silicone.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	16.00

Subtotal for Job #6: 16.00

Parts Total:	14.82
Labour Total:	48.00
Sublet Total:	0.00
Extras Total:	17.25
WORK ORDER TOTAL:	80.07

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 71370



Customer #: 53405
SHAFFER, DEBB K.

