



Warranty Authorization Form

Date: 8/31/2023

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 44931 Unit: 7M5FP4225RB203619
Series: Paradigm Model: 2024PAR382RK
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 20010B FAUCET - BATHROOM - REPLACE (Photos required)(part return per auth) Fault Code: VENDOR

Serial #: Model #: Notes: 8/15/23: Danielle -- Approved pending the testing of the components, if the components test good they will be charged back to you. Thank you.

Problem: THE HALF BATH FAUCET IS LEAKING. WATER IS COMING OUT AT THE HANDLE Time Requested: .5
Cause: Faucet Time Allowed: .5
Remedy: Got pictures of faucet and filled out sheet to order Sublet Repairs: 0.00
Part Return Req: Yes
Status: Approved

Operation Line 2

Flat Rate Code: 16081 ROOF VENT - WALL CONTROL - REPLACE - MAXXAIR Fault Code: IMPROPERLY INSTALLED
(MODEL AND SERIAL NUMBER OF THE UNIT IS REQUIRED)(RVP auth required)

Serial #: NA Model #: NA Notes:

Problem: THE MAX AIR FAN IN THE KITCHEN IS NOT WORKING Time Requested: .25
Cause: Fan in kitchen dosent work Time Allowed: .25
Remedy: took fantastic fan shroud dwn to see if it had power and it does,took off controller on wall and found out it is wrong controller,it had a 8 pin controller in it it needs 6 pin controller,filled out sheet and give to bin for approval. Sublet Repairs: 0.00
Part Return Req: No
Status: Approved