



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71451

CUSTOMER WORK ORDER

WO #: 71451 (Appointment Date: 15 AUG 2023 - Time: 10:30am)

Customer: 10088 - JAMES, MICHAEL W. Stock #: 11090

- 812-490-1474

Tag:

Author: BH

Location: 0820 CHECK PREAUTH

Stock Desc: (11090) 2022 COACHMEN

CATALINA 303RKDSLE

Chassis #: 5ZT2CAVB0NX025607

Serial #: 5ZT2CAVB0NX025607

Mileage:

Licence:

Invoice #:

Date In: 15 AUG 23

Promised:

Date Sched:

Completed: 16 AUG 23

Warr. Date: 30 JUL 22

Job #1 - Warranty

COMPLAINT: CUSTOMER HAS NOTICED WATER ON THE FLOOR OF THE BEDROOM. THIS IS THE FLOOR AREA BETWEEN THE BED AND THE BATHROOM WALL. WE ARE GOING TO TRY TO GET THIS REPAIR COVERED BY WARRANTY.

CAUSE: Cold side of outside shower

CORRECTION: Hooked camper to city water, then turned on the water. Turned on the inside shower and then checked the toilet for leaks. Looked inside the cubby hole where the water was run. Noticed on the backside of the outside shower on the cold side was dripping water. Took pictures of the water line dripping. Turned off the city water. Went to the outside of the outside shower and removed the screws holding it in. Pulled the outside shower from the wall and tightened the fitting. Turned on the city water to check for any further leaks. Put outside shower back in the wall and tightened the screws. Used clear silicone to trim out the outside shower.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	64.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Subtotal for Job #1: 64.00

Job #2 - Internal

COMPLAINT: TAPE UNDER THE CAMPER WHERE THE UNDER BELLY HAS COME LOOSE IT IS IN THE FRONT OF THE CAMPER

CAUSE: Bad tape job

CORRECTION: Remove most of the old tape, then put on extreme tape on the underbelly. Took pictures.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #2: 0.00



Customer #: 10088
JAMES, MICHAEL W.



W/O: 71451

Parts Total:	0.00
Labour Total:	64.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	64.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 Aug 2023



Customer #: 10088
JAMES, MICHAEL W.

