



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 71488  
Promised Date:  
24 AUG 23

### CUSTOMER WORK ORDER

WO #: 71488

Customer: 18834 - EGLI, MARK J. -  
812-682-2594

Tag: BH MADE APPT FOR 11-06

Author: BH

Location: 1215 CHECK STATUS WITH  
BB

Stock #: 10676

Stock Desc: 2022 TT COACHMEN  
CATALINA 243RBSLE

Chassis #: 5ZT2CANB2NU039607

Serial #: 5ZT2CANB2NU039607

Mileage: 0

Licence:

Invoice #:

Date In: 18 AUG 23

Promised: 31 AUG 23

Date Sched:

Completed: 13 DEC 23

Warr. Date: 29 APR 22

#### Job #1 - Warranty

COMPLAINT: FIX ALL THE DAMAGE IN THE UNIT JOBS ARE LISTED BELOW

CAUSE: Wallboard peeling.

CORRECTION: Cleaned off putty on ceiling of slideroom. Cleaned off putty on bedroom wall. Remove window in bedroom. Remove trim. Remove damaged panel. Take panel and trim edge to thickness of old panel. New panels are thicker than whats on the wall. Cut and install new panel and trim. Router out window. Install window. Putty holes. Remove couch. Remove valance. Remove window. Remove damaged panel. Cut and install new panel. Router out window. Put up new trim. Putty holes. Put new tape on window. Put window back. Put couch back and trim out base. Silicone above window. Remove bench seat. Remove trim. Remove valance and shade. Remove window. Remove damaged panel. Cut new panel and install. Router out window. Put window back. Silicone. Put valance back and shade. Put on new trim. Put bench seat back. Putty holes. Install new wall board on the rear cabinet inside. Trim out and putty. Trim around shower surround and silicone. Replace 3/4" piece of trim on left of shower. Remove bathroom cabinet and replace wall board. Put cabinet back and trim out. Remove small bar counter. Remove control board. Remove cabinet above sink. Remove stove vent. Remove all trim. Cut out and remove damaged panels. Put blocking in where needed. Cut and install new wall panel around door and counter top. Put on seam tape. Re install counter top. Put cabinet back. Put control board back. Trim out and fill holes. Put stove vent back. Silicone. Remove TV. Remove radio. Remove cabinet on TV wall. Remove damaged panels on TV wall and slideroom wall. Install new panels on slideroom wall. Install new panels on TV wall. Put on trim. Putty holes. Remove convertor. Remove damaged stile. Install new stile. Put back convertor. Remove damaged wood on TV cabinet. Replace with new stiles. Install cabinet. Put up TV.. put doors back. Put fire place back. Radio back. Silicone where needed.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	480.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	640.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	1,280.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	720.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	640.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	640.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	640.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	720.00



Customer #: 18834  
EGLI, MARK J.





**Parts**

Part #	Description	Qty	Price	Total
F100130689	SEAM TAPE - PER FT.	60.00	0.15	9.00
F100410661	VINYL BOARD,F4E VIPER TRUFFLE 3.6MM	10.00	48.99	489.90
F100130672	7/8" BATTEN VIPER TRUFFLE	20.00	1.86	37.20
6631	STILE, LC 18MM" X 5-1/4" X 8' SQUARE	16.00	1.52	24.32
F100285185	STILE, LC 18MM" X 2" X 8' SQUARE CHI	8.00	0.62	4.96
500627	CLEAR SIKASIL PLUS	1.00	16.59	16.59
72-7218	GFI RECEPTACLE - BLACK	1.00	16.33	16.33

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00
FRT	FREIGHT-BOARD, TAPE, BATTEN	1.00	234.71	234.71
FRT	UPS-STILES AND SEAM TAPE 11-10-23	1.00	105.95	105.95
FRT	UPS FREIGHT 11-13-23 - 2ND SET PANELS	1.00	173.88	173.88

**Subtotal for Job #1: 8,312.84**

**Job #2 - Warranty**

COMPLAINT: Wall paper to the right of the tv between bedroom door is peeling

CAUSE: Wallboard peeling

CORRECTION: Remove radio and speakers. Remove the whole cabin assembly on wall. Remove door jam.Remove damaged wallboard.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: In slide room front part of the slide not accent wall the paper is peeling

CAUSE: Wallboard peeling

CORRECTION: Remove window and valance and blind. Remove bench seat. Remove damage wallboard.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: Above kitchen sink paper is peeling in cabinet area

CAUSE: wallboard peeling

CORRECTION: Remove cabinet. Remove damage wallboard.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00





**Subtotal for Job #4: 0.00**

**Job #5 - Warranty**

COMPLAINT: In slide room rear wall paper is peeling not accent wall

CAUSE: Wallboard peeling.

CORRECTION: Remove window valance and blind. Remove couch. Remove damage wallboard.

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

**Subtotal for Job #5: 0.00**

**Job #6 - Warranty**

COMPLAINT: Inside cabinet next to bathroom and slide room paper is peeling

CAUSE: Wallboard is peeling..

CORRECTION: Remove cabinet. Remove damage wallboard..

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

**Subtotal for Job #6: 0.00**

**Job #7 - Warranty**

COMPLAINT: Above the slide room near the back paper peeling

CAUSE: Paper peeling

CORRECTION: Remove upper trim on slideroom. Remove damage wallboard.

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

**Subtotal for Job #7: 0.00**

**Job #8 - Warranty**

COMPLAINT: Near the entry door wall paper is peeling above the door

CAUSE: Wallboard peeling.

CORRECTION: Remove trim around entrance door. Remove damaged wall panel..

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

**Subtotal for Job #8: 0.00**

Parts Total: 598.30  
 Labour Total: 7,200.00  
 Sublet Total: 0.00  
 Extras Total: 514.54  
**WORK ORDER TOTAL: 8,312.84**



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 13 Dec 2023

Customer Signature : \_\_\_\_\_

W/O: 71488  
Promised Date: 31 AUG 23



Customer #: 18834  
EGLI, MARK J.

