



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71494
Promised Date:
24 AUG 23



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 71494

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag: CLOSE IN AUG

Author: PH

Location: 0906 WAITING FOR PREAUTH
TO BE APPROVED

Stock #: 11185

Stock Desc: 2024 TT KEYSTONE
SPRINGDALE 260BHC

Chassis #: 4YDTSGL20R7100209

Serial #: 4YDTSGL20R7100209

Mileage: 0

Licence:

Invoice #:

Date In: 18 AUG 23

Promised: 31 AUG 23

Date Sched:

Completed: 31 AUG 23

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*71575 on 30 AUG 23

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

CAUSE: Pdi unit

CORRECTION: Started pdi with bringing camper to service bay. Got a new battery box and filled the 20 lb lp tanks. Plugged in shore power cord from camper. Hooked up a test battery. Had to move lp tank mount forward towards the tongue jack to make battery box to fit. Checked torque on lug nuts of 110 ft lbs. Checked tire psi at 75. Jacked up the camper to pull the brakeaway switch to test breaks and the pull cable broke, got with Ben to replace the breakaway switch. Changed on another job line. Finished testing brakes and running lights with test box. Inspected the tongue coupler, chains and jack. Filled fresh tank to test the water pump, water heater, and faucets. Turned on AC, interior lights. Checked all outlets/gfci, USB, smoke detector, lp/co detector. Used the test TV at all 3 TV locations to check for TV signal. Turned on gas to run water heater, furnace for lp drop test and stove burners. Checked the converter output of 13.67 volts. Made sure 12v fridge works. Turned on kitchen faucet, shower, and bathroom faucet for hot water. System is not winterized. Filled grey and black tank to check sensor level. Checked faucet drains, water lines for leaks. Emptied the black, grey, fresh tank. Checked the black tank flush and looked for leaks. Checked windows and emergency windows, blinds, vents, vent fans. Checked drawers, cabinets, storage compartment. Tested the microwave and hood range. Ran awning out and in, turned on the LED lights. Checked keys and locks. Setup kitchen table. Took pictures for paperwork. Inspected the roof.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: CABLE FOR THE BRAKE AWAY HAS CAME LOOSE

CAUSE: Breakaway cable broke

CORRECTION: Went to pull breakaway cable and it broke when pulled, the plug never came out. Got with Ben to install new breakaway switch. Cut out bad breakaway switch then spliced in new breakaway switch. Took pictures. Tested.



W/O: 71494
Promised Date: 31 AUG 23



Customer #: 1000
BASDENS AMERICAN RV,



Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	80.00

Parts

Part #	Description	Qty	Price	Total
80-00-2060	Trailer Breakaway System Switch; Zip	1.00	21.01	21.01

Subtotal for Job #1: 101.01

Parts Total: 21.01
Labour Total: 80.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 101.01

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 06 Sep 2023

Customer Signature : _____

