

# e-Authorization

8/25/20  
10:49:27

3-Authorization number PA03515489 Reference no: 71499 Status: Approved Approved by johnj  
 Billing Name Address Address VIN Retail sold on Approved date 8/24/2023

34 Basden's American RV Basden's American RV 4YDTSGP27P3100738  
 600 E Baseline Rd  
 Evansville, IN 47725

| Job operation | Description                | Sublet | Sub hours | Approved hours | Actual hours | Qty | Base hours | Complaint / Cause / Correction  |
|---------------|----------------------------|--------|-----------|----------------|--------------|-----|------------|---|
| 1             | 5101906B Light, Clearance  | 0.00   | 0.30      | 0.20           |              | 1   | 0.20       | Complaint:REAR TOP MARKER LIGHT BAD<br>Cause:light<br>Correction:rear top marker light was dim,got new light and took off old light and undid wires and rewired new light in place and resaled.<br>KRV-VCB  |
| 2             | 4209314A TV Lift Mechanism | 0.00   | 0.40      |                |              | 1   | 0.20       | Complaint:LIVING ROOM TV CROOKED<br>Cause:TV crooked<br>Correction:Unplugged tv and coax took tv down and took screws out of bracket and moved straight and put screws back in and installed tv and plugged in and coax,now it is straight.<br>KRV - The submitted item is considered acceptable in regards to functionality and aesthetic appearance as stated in Keystone RV's Policy and Procedure Manual. |

3-Authorization number PA03515489 0.20

paper claims only use one pre-authorization number per warranty claim for  
 please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim  
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the