

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1690260
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKY29PK085838
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	094 / 094A
Labor rate:	\$160.00	ITEM #	CKT23MKBL-94
OWNER INFORMATION		DEALER RO #	71630
		CLAIM START DATE	09/27/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	30-99-03-00-001030	Valance - Interior/Soft Goods/Install/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2023-09-27 16:00:53 :: VALANCE AND BLIND FELL DOWN BEHIND DINNETTE WINDOW VALANCE AND ROLLER SHADE FELL DOWN Window valance wood is split at mounting points. Roller shade is bent and will not stay in mounting clips. Parts need replaced. Turned in parts request for a new window valance and a new roller shade. 9/27/23: Received new parts. Transferred shade mounting clips from damaged part to new part. Added extra Brad nails to hold valance together. Mounted roller shade and curtains to new valance. Mounted new valance and new roller shade over dinette window. Secured in place with screws. Moved unit back to show room.	
	Model #	Dlr Sub Hrs 0.50 Sub Labor Amt \$80.00
	Serial #	Appr Hrs 0.20 Appr Labor Amt \$32.00
	Notes	
	thank you	

Submitted	Labor Amt	\$80.00	Approved	Labor Amt	\$32.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$80.00		Total	\$32.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.