



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71672
Promised Date:
16 SEP 23

CUSTOMER WORK ORDER

WO #: 71672

Customer: 54027 - SETSER, LISA -
217-474-3805

Tag: BEN SENT IN PREAUTH

Author: BH

Location: 0921 BH TO CLOSE

Stock #: 11167

Stock Desc: 2024 TT KEYSTONE
SPRINGDALE 260BHC

Chassis #: 4YDTSGL20R7100081

Serial #: 4YDTSGL20R7100081

Mileage: 0

Licence:

Invoice #:

Date In: 13 SEP 23

Promised: 16 SEP 23

Date Sched:

Completed: 21 SEP 23

Warr. Date: 16 SEP 23

Job #BUNKFINAL - Internal

COMPLAINT: FINAL PDI NEW BUNKHOUSE

CAUSE: BUNKFIN. FINAL PDI NEW BUNKHOUSE

CORRECTION: Moved unit into shop from sales lot. Installed new battery. Tongue jack trips circuit breaker. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 75 psi. Recorded all tire serial numbers. Checked roof and awning. Checked power cord. Checked electric stab jacks. Checked all interior lights. Checked converter output. Added water to fresh water tank and flushed water lines and faucets. Connected to city water. Performed LP drop test and set LP pressure at 10 in.wc. Operated all appliances. Moved unit outside and checked TV Antenna. Drained all holding tanks. Moved unit to washbay area.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #BUNKFINAL: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: E2 10K E2 EQUALIZER HITCH

Installed hitch head. Adjusted brackets. Hooked up unit to truck. Tested lights.

CORRECTION: Install hitch brackets on frame of unit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C

Customer #: 54027
SETSER, LISA



Subtotal for Job #E2: 0.00

Job #1 - Warranty

COMPLAINT: TOUNGE JACK IS NOT WORKING

CAUSE: TONGUE JACK NOT WORKING

CORRECTION: Checked built in circuit breaker on jack. Is not working. Jack needs replaced. Removed damaged tongue jack. Mounted new tongue jack. Rewired for new jack. Checked operation of new jack.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	0.00
Z990	MISCELLANEOUS REPAIR	DKM	80.00

Parts Part #	Description	Qty	Price	Total
3291	3500# STROMBERG ELEC JACK -BULK	1.00	189.75	189.75

Subtotal for Job #1: 269.75

Parts Total: 189.75
Labour Total: 80.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 269.75

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 21 Sep 2023

W/O: 71672
Promised Date: 16 SEP 23



Customer #: 54027
SETSER, LISA

