



Warranty Authorization Form

Date: 9/22/2023

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 47590 Unit: 7M5FV4432NA006354
Series: Valor Model: 2022VAL41V15
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 14083 TRIM - DECORATIVE WOOD -
REPAIR

Fault Code: IMPROPERLY INSTALLED

Serial #:

Model #:

Notes:

Problem: THE WOOD TRIM THAT GOES IN THE BATHROOM IS COMING OFF THE WALL AND
NEEDS TO BE REATTACHED

Time Requested: .3

Cause: Wood trim to long

Time Allowed: .3

Remedy: Took picture of wood trim coming off wall. Cut 1/8 off the length then stapled back to the
bathroom wall. Trimmed with wood putty to hide the staples.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved