



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71717



CUSTOMER WORK ORDER

WO #: 71717

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag: BH GAVE TO DGH 9-27
Author: BH
Location: 1005 CHECK WORK

Stock #: 11276
Stock Desc: 2024 TT COACHMEN
CATALINA SUMMIT SERIES 231MKS
Chassis #: 5ZT2CAMB7RU042400
Serial #: 5ZT2CAMB7RU042400
Mileage: 0
Licence:

Invoice #:
Date In: 19 SEP 23
Promised:
Date Sched:
Completed: 30 SEP 23
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: pdi

CORRECTION: did pdi and everything on sheet,checked lp , water ,electrical and appliances.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: RR STAB JACK ROD IS BENT

CAUSE: Bent rod on scissor jack

CORRECTION: took pics of jack.took out bolts and took off old jack and installed new jack.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	24.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	24.00

Parts

Part #	Description	Qty	Price	Total
C01283376	JACK, SCISSOR BEARCLAW 24" 5000# W/S	1.00	31.41	31.41

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-JOBS 1,4	1.00	17.30	17.30

Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 96.71

Job #2 - Warranty

COMPLAINT: FRIDGE DOOR ON THE BOTTOM HAS 2 DENTS IN TI

CAUSE: Dent in bottom door

CORRECTION: Took pics of ref.had to take out 8 screws and pull ref out to get to bracketstook off bottom bracket and slide door out,transferred all hinges and covers to new door,installed door and put hinge back in place,pushed ref back in place and screwed down,transferred shelves in new door.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
F100282070	GE STAINLESS REFER DOOR 2022 MODEL G	1.00	542.04	542.04

Other Services

Code	Description	Qty	Price	Total
FRT	FED-EX - REFER DOOR	1.00	17.39	17.39

Subtotal for Job #2: 591.43

Job #3 - Warranty

COMPLAINT: BEDROOM DOOR OFF TRACK

CAUSE: Bedroom door

CORRECTION: Bedroom door off track,put door back on track and adjusted,

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	48.00

Subtotal for Job #3: 48.00

Job #4 - Warranty

COMPLAINT: BATHROOM LIGHT MISSING COVER

CAUSE: Light cover

CORRECTION: Took pics of missing light cover.installed new lens.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
C01297663	4.5 INCH LED LIGHT PUCK BASE WITH LE	1.00	2.19	2.19

Subtotal for Job #4: 34.19

W/O: 71717



Customer #: 1000
BASDEN'S AMERICAN RV,



Parts Total: 575.64
Labour Total: 160.00
Sublet Total: 0.00
Extras Total: 34.69
WORK ORDER TOTAL: 770.33

W/O: 71717

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 02 Oct 2023

Customer Signature : _____



Customer #: 1000
BASDEN'S AMERICAN RV,

