



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71796
Promised Date:
24 OCT 23

CUSTOMER WORK ORDER

WO #: 71796

Customer: 41377 - LENTS, JASON C. -
812-630-4537

Tag:

Author: CAM

Location: 1115 CHECK WORK

Stock #: 10053

Stock Desc: 2019 TT KEYSTONE
SPRINGDALE 311RE

Chassis #: 4YDT31129K3100686

Serial #: 4YDT31129K3100686

Mileage: 0

Licence:

Invoice #: 398437

Date In: 29 SEP 23

Promised: 31 OCT 23

Date Sched:

Completed: 31 OCT 23

Warr. Date: 19 JAN 19

Job #1 - External

COMPLAINT: ESTIMATE TO REPLACE AWNING FABRIC

CAUSE: Pulled unit into shop. Hooked up to shore power. Ran awning out. Zip tied awning legs. Cut awning fabric. Removed gutter spout. Removed awning tube. Awning tube is crushed in 2 spots. Waiting on parts. 10/20 customer wants us to try and use tube. Couldn't get awning spline to move. the tube has squeezed the track closed. Needs a new tube. Received new tube and fabric. Installed tube to hardware. Installed butt connections on wires for lights. Ran awning in and out to track. Repositioned awning. Installed set screw. Installed gutter spout. Sealed with silicone.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
593888	IDLER SIDE COVER - FRONT	1.00	N/C	N/C
593889	AWNING - BACK - COVER - SOLERA	1.00	N/C	N/C
510920	Awning - 18' - AWN1000 - Electric -	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
FRT	FREIGHT-FRTA	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #WINTER - External

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Ran antifreeze through all lines and fixtures. Drained all tanks, bypassed water heater

CORRECTION: .

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 41377
LENTS, JASON C.



Z990	WINTERIZE UNIT	ZMS	N/C
Z990	WINTERIZE UNIT	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #2 - External

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE THE BREAKAWAY CABLE REPLACED WITH A FASTWAY BREAKAWAY CABLE.

CAUSE: Installed fastway cable.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
80-01-2160	"ZIP" BREAKAWAY CABLE 6'	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - External

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE THE ANODE ROD REPLACED.

CAUSE: Removed anode rod from tank. Placed new anode rod in tank

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
09-0205	MAGNESIUM ANODE ROD - SUBURBAN	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - External

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE LOW POINT DRAIN CAPS FOR THE TRAILER. HE FORGOT TO PUT THOSE BACK ON.

CAUSE: Low point caps were in place. Fresh tank cap is missing. Replaced fresh tank cap and placed extra inside unit.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
10-7090	1pc 1/2" PLUG CAP	2.00	N/C	N/C



Subtotal for Job #4: 0.00

Job #5 - External

COMPLAINT: LARGE BLIND BEHIND THE RECLINER, WINDOW
NEXT TO RECLINER FACING THE BACK, AND
THE TWO REAR BLINDS DON'T OPEN

CAUSE: Took pics of data tags on blinds. Removed valances. Removed blinds. Received tube with blinds
from parts. Installed new blinds. Installed valances.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
594835	Shade - Night Only - 26" x 42" - PVC	1.00	N/C	N/C
594837	Shade - Night Only - 74" x 42" - PVC	1.00	N/C	N/C
594839	Shade - Night Only - 20" x 38" - PVC	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SHADES	1.00	N/C	N/C

Subtotal for Job #5: 0.00

Job #REGULATOR - Warranty

COMPLAINT: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414
SECTION:71 COMPONENT:414 OPERATION:7141442B

CAUSE: Regulator does not fall under recall.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	48.00

Subtotal for Job #REGULATOR: 48.00

Job #TIRE - External

DISMOUNT AND MOUNT TIRE REPLACE THE SPARE TIRE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
724857519	GY ENDURANCE 225/75R15 "E" TIRE	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
TDF	TIRE DISPOSAL FEE	0.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C

Subtotal for Job #TIRE: 0.00

W/O: 71796
Promised Date: 31 OCT 23



Customer #: 41377
LENTS, JASON C.



W/O: 71796
Promised Date: 31 OCT 23

Parts Total:	0.00
Labour Total:	48.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	48.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 09 Nov 2023



Customer #: 41377
LENTS, JASON C.

