



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71813
Promised Date:
05 OCT 23



CUSTOMER WORK ORDER

WO #: 71813

Customer: 54079 - IGLEHEART, KASEY - Stock #: 11262

812-698-9297

Tag: CLOSE TICKET AFTER

WARRANTY DONE

Author: BH

Location: 1031 CHECK PREAUTH

Stock Desc: 2023 TT FOREST RIVER
CHEROKEE GREY WOLF 29TE
Chassis #: 4X4TCKE23PX161612
Serial #: 4X4TCKE23PX161612
Mileage:
Licence:

Invoice #:

Date In: 02 OCT 23

Promised: 05 OCT 23

Date Sched:

Completed: 30 OCT 23

Warr. Date: 05 OCT 23

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: final pdi

CORRECTION: did final and everything on sheet,also checked lp system,water,appliances andelectric.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: hitch

CORRECTION: set up brackets on tongue.set up hitch inwalk thru area.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C
14-2930	EQUALIZER HITCH SHANK	1.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #1 - Warranty

COMPLAINT: FRIDGE HAS NO POWER

CAUSE: no power to ref

CORRECTION: checked breaker box and everything was good,took out ref and traced wires through floor,took out breaker box and found ground wire was not installed in fuse block,hooked up and still nothing,found fuse under ref and it was bad,replaced and now it works,installed ref back in place and breaker box.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 54079
IGLEHEART, KASEY



Z990 MISC LABOUR CODE (EXTERNAL) DGH 128.00

Subtotal for Job #1: 128.00

Job #2 - Warranty

COMPLAINT: FRONT SLIDE INSIDE BULB SEAL IS OFF

CAUSE: bulb seal

CORRECTION: installed bulb seal,very hard to get on,tightened up bracket screws they were loose.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	32.00

Subtotal for Job #2: 32.00

Job #3 - Warranty

COMPLAINT: HANDLE FOR SHOWER DOOR NOT HOLDING WITH SCREW

CORRECTION: SWAPPED RUBBER WHERE IT WAS THINNERAND IT NOT SCREW CATCHES.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

Subtotal for Job #3: 0.00

Parts Total: 0.00
 Labour Total: 160.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 160.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 Oct 2023

W/O: 71813
Promised Date: 05 OCT 23



Customer #: 54079
IGLEHEART, KASEY

