

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 72015
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 50350 - DAVID FISCHER
Address: 5512 RYAN LN

47712

Phone: 8127745016

Stock Number: 2022 CATALINA 5ZT2CAZB8NX026806

VIN: 5ZT2CAZB8NX026806 HIN:

SER#: 5ZT2CAZB8NX026806

Mileage: Work Order Comp: 26 DEC 23

Auth. No: Dealer #:

Warr. Date: Work Order Date: 16 OCT 23 Inv #: 399611

WO # Job # Description JOB INFORMATION

72015 1 Tongue Jack light switch missing
FOUND SWITCH MISSING

72015 2 Vinyl inset in big slide on top is smaller
Removed insert trim that has shrunk. Installed new insert trim.
.

72015 5 Sliding glass door in front bed room wont move easy like the
other one will
Front door came out of track. Both doors are rubbing the bottom
track. Adjusted both doors. Set front door in track. Plastic
latch for door is broken. Needs a new latch. Pictures on ids.
.

72015 6 Water coming in the washer area you can see paper peeling on the
door side wall on top and above the door
Ran sprinkler on the roof for 4 1/2 hours. No water is coming
through the ceiling. Panels are peeling like the rest of them.
Need to replace panels.
.

72015 3 Front bed room front fascia has came off on the bottom
Removed fascia. Removed and set Brad nails. Found new screws for
fascia support. Installed new screws. Secured wall panel and trim
to fascia support. Installed fascia. Cleaned up area.
.

Claim : 72015

 WO # Job # Description JOB INFORMATION

72015 9 Wood panel on front slide is loose under bed
 Panel came loose. Secured panel with Brad nails.
 .

72015 11 In rear bunk area the last ceiling panel is loose
 Applied brad nails to ceiling panel as needed. Filled holes with
 putty.
 .

 Part No Job# Description PARTS Qty Price Total

226018	1	226018 JACK LIGHT SWITCH - LIPPER		1.00	19.55	19.55
RVDE369	2	E369 BLACK HD 1" x 25' INSERT TRI		1.00	8.53	8.53
RVDH527	5	H527 SLIDING MIRROR DOOR LATCH		1.00	5.42	5.42
F100130702	6	TAPE, SEAM VINYL 1" - 150' ROLL -		50.00	0.15	7.50
F100130689	6	SEAM TAPE - PER FT.		50.00	0.15	7.50
F100285188	6	3" CABINET STILE		8.00	0.91	7.28
F100285185	6	STILE, LC 18MM" X 2" X 8' SQUARE		8.00	0.62	4.96

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.10	160.00	16.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.30	160.00	48.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		9.51	160.00	1521.60
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		3.49	160.00	558.40
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.62	160.00	99.20
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.34	160.00	54.40
Z990	6	MISC LABOUR CODE (EXTERNAL)		1.00	160.00	160.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		1.04	160.00	166.40
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	9	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	11	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00

 Excode Job# Description EXTRAS Qty Price Total

SS	1	SHOP SUPPLIES		1.00	0.00	0.00
FRT	6	UPS-SEAM TAPE		1.00	17.29	17.29
FRT	6	UPS-STILES		1.00	32.36	32.36

Claim : 72015

```
*****
Excode   Job#  Description      EXTRAS          Qty    Price    Total
*****
```

```
Parts Total:      60.74
Labour Total:    2,752.00
Sublet Total:       0.00
Extras Total:     49.65
```

>>>> Claim Total: 2,862.39

Customer Signature: _____

Date: _____