

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 72137  
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO  
Customer: 54127 - BRITTANY DIXON  
Address:

, IN  
Phone: (615) 739-2066

Stock Number: 2022 MONTANA HIGH COUNTRY

VIN:

HIN:

SER#: 4YDFHMT21NA742686

Mileage:

Work Order Comp: 16 NOV 23

Auth. No:

Dealer #: 1194

Warr. Date:

Work Order Date: 27 OCT 23

Inv #: 398711

\*\*\*\*\*

WO # Job # Description JOB INFORMATION

\*\*\*\*\*

72137 2 TOILET IS LEAKING

Toilet valve  
Hooked up city water to camper. Flushed the toilet and noticed water coming from the flush handle. Removed the toilet to bench test for a proper leak. Removed the toilet valve the pushed the valve in for water to pass thru. Water was coming out where you push on the valve to flush. Took pictures. Put in po for warranty. Received a new toilet valve per Matt. Removed the bad valve then placed in the new toilet valve. Turned on the city water, flushed the toilet and checked for any further leaks. No leaks were found after replacing the toilet valve.

72137 4 CLOSET SLIDING DOOR TRACKS ARE BROKEN

Cracked mirror, mirror came off the track at top and bottom. Inspected the sliding mirror doors and tracks. Tracks are not broken. Found a cracked mirror, the secondary door was off the track at the top and bottom. Set the mirror door back on the top and bottom track. The first mirror door was off its bottom track. Set the first door back on its track. Put in po for a new sliding mirror door with measurements and pictures.

\*\*\*\*\*

Part No Job# Description PARTS Qty Price Total

\*\*\*\*\*

385311641 2 310 WATER VALVE - SEALAND 1.00 53.82 53.82

630124 4 Closet - Mirrored Door - 21" x 69 1.00 103.03 103.03

\*\*\*\*\*

Lab Code Job# Description LABOUR Hrs Rate Total

\*\*\*\*\*

Z990 2 MISCELLANEOUS REPAIR 0.00 160.00 0.00

Claim : 72137

```
*****
Lab Code  Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      2    MISCELLANEOUS REPAIR          0.75    160.00    120.00
Z990      2    MISCELLANEOUS REPAIR          0.00    160.00     0.00
Z990      4    MISCELLANEOUS REPAIR          0.52    160.00    83.20
Z990      4    MISCELLANEOUS REPAIR          0.48    160.00    76.80
*****
```

```
*****
Excode    Job#  Description          EXTRAS          Qty      Price      Total
*****
FRT       4    UPS FREIGHT 11-13-23 - DOOR    1.00    155.01    155.01
*****
```

Parts Total: 156.85  
Labour Total: 280.00  
Sublet Total: 0.00  
Extras Total: 155.01

>>>> Claim Total: 591.86

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_