

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 72172
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11166 - 2023 MONTANA HIGH COUNTRY 331RL 4YDFHMS23PA740233
VIN: 4YDFHMS23PA740233 HIN: SER#: 4YDFHMS23PA740233
Mileage: 0 Work Order Comp: 26 DEC 23
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 30 OCT 23 Inv #: 399606

WO # Job # Description JOB INFORMATION

72172 2 DOORSIDE SLIDE ROOM REAR WINDOW LEAKING WHEN LOOKING AT THE COUCH
ITS TOO THE RIGHT
Window leak
Remove couch. Remove the valance. Remove window. Remove outlet and
light switch. Remove trim. Remove wall panel. Put a new wall
panel. Put on new trim. Put new foam tape on widow. Put window
back. Silicone on top of window

72172 1 DOORSIDE REAR WINDOW LEAKING WHEN LOOKING AT THE COUCH TO THE
LEFT
Window leak
Remove window. Put on new foam tape. Put window back. Silicone
top of window

Part No Job# Description PARTS Qty Price Total

6269 2 Panel - 2.7mm x 48" x 96" - Carb 1.00 52.85 52.85
636349 2 Trim - Batten - 3.0mm x 7/8" x 96 2.00 2.53 5.06
8350 2 Trim - Batten - 3.6mm x 1 3/8" x 1.00 3.12 3.12

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISCELLANEOUS REPAIR 1.65 160.00 264.00
Z990 2 MISCELLANEOUS REPAIR 0.10 160.00 16.00
Z990 2 MISCELLANEOUS REPAIR 0.04 160.00 6.40

Claim : 72172

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      2    MISCELLANEOUS REPAIR      3.21    160.00    513.60
Z990      1    MISCELLANEOUS REPAIR      0.00    160.00      0.00
Z990      1    MISCELLANEOUS REPAIR      0.00    160.00      0.00
Z990      1    MISCELLANEOUS REPAIR      1.00    160.00    160.00
Z990      1    MISCELLANEOUS REPAIR      0.00    160.00      0.00

```

```

*****
Excode    Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT        2    FREIGHT & CRATE - PANEL & TRIM      1.00    155.01    155.01

```

```

Parts Total:      61.03
Labour Total:     960.00
Sublet Total:      0.00
Extras Total:     155.01

```

>>>> Claim Total: 1,176.04

Customer Signature: _____

Date: _____