



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72172
Promised Date:
20 NOV 23



Customer #: 1000
BASDENS AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 72172

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 1226 CHECK STATUS WITH
BB

Stock #: 11166
Stock Desc: 2023 5W KEYSTONE
MONTANA HIGH COUNTRY 331RL
Chassis #: 4YDFHMS23PA740233
Serial #: 4YDFHMS23PA740233
Mileage: 0
Licence:

Invoice #:
Date In: 30 OCT 23
Promised: 30 NOV 23
Date Sched:
Completed: 26 DEC 23
Warr. Date:

Job #1 - Warranty

COMPLAINT: DOORSIDE REAR WINDOW LEAKING WHEN LOOKING AT THE COUCH TO THE LEFT

CAUSE: Window leak

CORRECTION: Remove window. Put on new foam tape. Put window back. Silicone top of window

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	160.00
Z990	MISCELLANEOUS REPAIR	BB	0.00

Subtotal for Job #1: 160.00

Job #2 - Warranty

COMPLAINT: DOORSIDE SLIDE ROOM REAR WINDOW LEAKING WHEN LOOKING AT THE COUCH
ITS TOO THE RIGHT

CAUSE: Window leak

CORRECTION: Remove couch. Remove the valance. Remove window. Remove outlet and light switch.
Remove trim. Remove wall panel. Put a new wall panel. Put on new trim. Put new foam tape on widow. Put
window back. Silicone on top of window

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	264.00
Z990	MISCELLANEOUS REPAIR	BB	16.00
Z990	MISCELLANEOUS REPAIR	BB	6.40
Z990	MISCELLANEOUS REPAIR	BB	513.60

Parts

Part #	Description	Qty	Price	Total
6269	Panel - 2.7mm x 48" x 96" - Carb 2	1.00	52.85	52.85
636349	Trim - Batten - 3.0mm x 7/8" x 96" -	2.00	2.53	5.06
8350	Trim - Batten - 3.6mm x 1 3/8" x 96"	1.00	3.12	3.12

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT & CRATE - PANEL & TRIM	1.00	155.01	155.01

Subtotal for Job #2: 1,016.04



W/O: 72172
Promised Date: 30 NOV 23

Parts Total:	61.03
Labour Total:	960.00
Sublet Total:	0.00
Extras Total:	155.01
WORK ORDER TOTAL:	1,176.04

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Dec 2023



Customer #: 1000
BASDEN'S AMERICAN RV,

