



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72198
Promised Date:
20 NOV 23

CUSTOMER WORK ORDER

WO #: 72198 (Appointment Date: 02 NOV 2023 - Time: 07:00am)

Customer: 43863 - DEVINE, BARRY -

Tag:

Author: PH

Location: 1110 BH TO CLOSE

Stock #: 11142

Stock Desc: (11142) 2023 KEYSTONE

COUGAR HALF-TON 29RLI

Chassis #: 4YDFCGN25P2501305

Serial #: 4YDFCGN25P2501305

Mileage:

Licence:

Invoice #: 398535

Date In: 02 NOV 23

Promised: 30 NOV 23

Date Sched:

Completed: 10 NOV 23

Warr. Date: 13 JAN 23

Job #WINTER - External

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Ran a.f. through all lines and fixtures. Drained all tanks.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #2 - Warranty

COMPLAINT: EHXAUST FAN NOT WORKING IN THE BATHROOM

CAUSE: Switch is broken. Removed shroud, handle and screen from vent. Removed broken switch.

Installed new switch,screen,handle and shroud. Cleaned up mess.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	32.00

Parts

Part #	Description	Qty	Price	Total
212097	S731 PUSH BUTTON ON-OFF SWITCH	1.00	6.99	6.99

Customer #: 43863
DEVINE, BARRY



Subtotal for Job #2: 38.99

Job #3 - Internal

COMPLAINT: THE DUMP FOR THE KITCHEN GALLY THE HANDLE FELL OFF

CAUSE: Looked for missing or damaged parts. Couldn't find anything. Asked service writer about issue.

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Subtotal for Job #3:			0.00

Job #4 - Internal

COMPLAINT: CHECK SLIDE ROOM CABLES TO SEE IF THEY ARE CORRECT. CUSTOMER STATES THEY SEEM LOOSE

CAUSE: Ran both slide rooms in and out several times. Checked tension on all cables. There is slight play in the cables but nothing out of tolerance or that's causing the rooms to have problems.

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Subtotal for Job #4:			0.00

Parts Total: 6.99
Labour Total: 32.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 38.99

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Nov 2023

W/O: 72198
Promised Date: 30 NOV 23

Customer #: 43863
DEVINE, BARRY

