

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 72253
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11294 - 2024 FREEDOM EXPRESS 298FDS 5ZT2FEVB9RW028659
VIN: 5ZT2FEVB9RW028659 HIN: SER#: 5ZT2FEVB9RW028659
Mileage: 0 Work Order Comp: 30 NOV 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 07 NOV 23 Inv #: 399137

WO # Job # Description JOB INFORMATION

72253 2 FRONT GREY TANK DUMP VALVE WILL NOT CLOSE
FRONT GREY TANK DUMP VALVE WILL NOT CLOSE
Water drained out of tank very slowly. When tank was empty,
valve would not close. Removed sewer pipe end and dump valve from
drain pipe. Drain pipe clogged with debris from tank
installation. Also excess glue blocking drain valve. Installed
new sewer cap end and mating parts. Used original dump valve as
it did not have glue on it. Added water to tank and checked for
leaks. No leaks.

72253 1 ROADSIDE MIDDLE CLEARANCE LIGHT NOT WORKING
ROADSIDE MIDDLE CLEARANCE LIGHT NOT WORKING
Removed middle light. Found wires on light were connected
backwards. Removed wire crimes. Rewired light with black to
positive and white to ground. Checked operation of rewired light.
OK. Cleaned off old silicone around light. Remounted light and
resealed with clear silicone.

Part No Job# Description PARTS Qty Price Total

VLPT1006-1 2 GRENTEC 1-1/2" SPIGOT 1.00 2.35 2.35
VLPT1041-1 2 T1041-1 TANK ADAPTOR 1.00 2.91 2.91
VLPT1029-2 2 GRENTEC TERMINATION ADPT. 1.00 2.82 2.82

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISC LABOUR CODE (EXTERNAL) 2.50 160.00 400.00

Claim : 72253

```
*****  
Lab Code Job# Description LABOUR Hrs Rate Total  
*****  
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00  
  
Parts Total: 8.08  
Labour Total: 432.00  
Sublet Total: 0.00  
Extras Total: 0.00  
  
>>>> Claim Total: 440.08
```

Customer Signature: _____

Date: _____