



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 72291  
Promised Date:  
20 DEC 23

## CUSTOMER WORK ORDER

WO #: 72291

Customer: 54208 - WILSON, CHAD H. -  
812-444-9164

Tag: BH - 11-14-23 MAB ORDERED  
MONITOR NDA. 11-14-23

Author: BH

Location: 1205 CHECK PREAUTH GET  
WITH CHAD ABOUT WIRING

Stock #: 11186

Stock Desc: 2022 5W ALLIANCE RV  
VALOR 41V15

Chassis #: 7M5FV4432NA006354

Serial #: 7M5FV4432NA006354

Mileage: 0

Licence:

Invoice #:

Date In: 10 NOV 23

Promised: 30 DEC 23

Date Sched:

Completed: 30 NOV 23

Warr. Date: 17 NOV 23

### Job #FPDINFW - Internal

COMPLAINT: FINAL PDI ON NEW FIFTH WHEELS

CAUSE: final

CORRECTION: did final and everything on paper work check lp,water ,appliances and electrical,alsomade labels for fuel tanks,black tank handles were missing,and black tank cap missing,this was a tri axle,aired up all 7 ties had to get dot numbers,tested all 3 acs and furnance,checked ramp and all 3 awnings and roof.

### Labor

| Code   | Description                         | Mechanic | Total |
|--------|-------------------------------------|----------|-------|
| PDINFW | FINAL PDI NEW FIFTH WHEEL (INTERNAL | DGH      | N/C   |
| PDINFW | FINAL PDI NEW FIFTH WHEEL (INTERNAL | DGH      | N/C   |

### Parts

| Part #  | Description                       | Qty  | Price | Total |
|---------|-----------------------------------|------|-------|-------|
| 11-0649 | T58 TWIST ON VALVE                | 1.00 | N/C   | N/C   |
| 11-0429 | 39463 SEWER CAP W/HOSE CONNECTION | 1.00 | N/C   | N/C   |
| 5516    | A10-3050FHVP 30M-50F PIGTAIL      | 1.00 | N/C   | N/C   |
| 298640  | BRISTOL CABLE PULL HANDLE         | 1.00 | N/C   | N/C   |
| 27910   | 36543 PUMP WINTERIZATION KIT      | 1.00 | N/C   | N/C   |
| 210628  | MCL0032RBS 1-LED RED MARKER LIGHT | 1.00 | N/C   | N/C   |

Subtotal for Job #FPDINFW: 0.00

### Job #1 - Internal

COMPLAINT: INSTALL GENERATOR

CAUSE: generator

CORRECTION: got generator on skid and brought to front of camper and other assy,put in plate on floor and traced to cut out,cut out floor and drilled 6 holes,drilled hole in top and side for 12 volt wires and 110 wires,made cables for 12 volt side and hooked up,installed 2 gas lines and secured,installed generator and installed 6 boltshad to reem holes to fitput in 9 gallons of gas and tried to start,generator will not start.bill and i tried priming it and we are getting fuel to bowl,but it will not start,will look at it again tomorrow.tried to start again and it wouldnt,squeezed hose where i found a kink in it and it ran for 20 seconds,took off line and cut out pinched line,installed a straight in it,still wont run,took air filter off and got to gas line to see if it was gettting fuel and fuel pump getting a little fuel it sounded like it was starving for gas,blew air through line to tank to see if it would garggle it didnt,added 5 more gallons of gas,total of 15 gallons,primed pump up and got gas out of hose,then put geterator back together,it then started and ran,punched hole in electrical box and ran 110 wires to box and hooked up wires and taped,then installed exhaust pipe to generator and ran across camper and cut to fit hanger for exhaust,hooked up and drilled hole for hanger,tested and turned



Customer #: 54208  
WILSON, CHAD H.



on ac and it works,all good.

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | N/C   |

#### Parts

| Part # | Description         | Qty  | Price | Total |
|--------|---------------------|------|-------|-------|
| 23011  | IN LINE FUEL FILTER | 1.00 | N/C   | N/C   |

**Subtotal for Job #1: 0.00**

#### Job #2 - Internal

COMPLAINT: FIX WIRING FOR A PREPED GENSET FROM A CUMMINS TO A NPS

CORRECTION: RAN WIRING TO MATCH NEW GNESET.

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | BRM      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BRM      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BRM      | N/C   |

**Subtotal for Job #2: 0.00**

#### Job #3 - Warranty

COMPLAINT: THE BATTERY MONITOR IS NOT DISPLAYING ANYTHING

CAUSE: battery monitor

CORRECTION: installed battery monitor and had to recalibrate monitor.

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | 80.00 |

#### Parts

| Part # | Description            | Qty  | Price  | Total  |
|--------|------------------------|------|--------|--------|
| 13396  | MONITOR - BATTERY 500A | 1.00 | 150.99 | 150.99 |

#### Other Services

| Code | Description | Qty  | Price | Total |
|------|-------------|------|-------|-------|
| FRT  | UPS-MONITOR | 1.00 | 29.60 | 29.60 |

**Subtotal for Job #3: 260.59**

#### Job #4 - Warranty

COMPLAINT: THE BATHROOM DOOR TRIM CAME OFF.

CAUSE: door opening trim

CORRECTION: put trim back in place and put in screws to secure trim to wall.

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | 8.00  |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | 8.00  |

**Subtotal for Job #4: 16.00**

#### Job #5 - Warranty

COMPLAINT: THE KITCHEN CABINET DOOR WILL NOT LATCH

CAUSE: kitchen cabinet door latch

W/O: 72291  
Promised Date: 30 DEC 23



Customer #: 54208  
WILSON, CHAD H.



CORRECTION: took off latch on cabinet and moved to hit magnet.

**Labor**

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | 16.00 |

**Subtotal for Job #5: 16.00**

**Job #6 - Internal**

KEYS FOR CUSTOMER

**Parts**

| Part #  | Description       | Qty  | Price | Total |
|---------|-------------------|------|-------|-------|
| 20-0798 | GLOBAL KEY BLANKS | 4.00 | N/C   | N/C   |

**Other Services**

| Code  | Description | Qty  | Price | Total |
|-------|-------------|------|-------|-------|
| PARTS | KEY CUT     | 4.00 | N/C   | N/C   |

**Subtotal for Job #6: 0.00**

**Job #CAMERA - Internal**

INSTALL WIRELESS CAMERA

**Labor**

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DKM      | N/C   |

**Parts**

| Part # | Description                   | Qty  | Price | Total |
|--------|-------------------------------|------|-------|-------|
| 729936 | FURRION 7" REAR CAMERA SYSTEM | 1.00 | N/C   | N/C   |

**Other Services**

| Code | Description   | Qty  | Price | Total |
|------|---------------|------|-------|-------|
| SS   | SHOP SUPPLIES | 0.00 | N/C   | N/C   |

**Subtotal for Job #CAMERA: 0.00**

Parts Total: 150.99

Labour Total: 112.00

Sublet Total: 0.00

Extras Total: 29.60

**WORK ORDER TOTAL: 292.59**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 04 Dec 2023

W/O: 72291  
Promised Date: 30 DEC 23

Customer #: 54208  
WILSON, CHAD H.