

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 72388
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 10245 - CHAD T. PRICE
Address: 1118 DORAL ST MT CARMEL, IL

62863

Phone: 618-263-7854

Stock Number: 10871 - 2023 CATALINA 313RLTSLE 5ZT2CAWB2PX028798

VIN: 5ZT2CAWB2PX028798 HIN: SER#: 5ZT2CAWB2PX028798

Mileage: 0 Work Order Comp: 28 NOV 23

Auth. No: Dealer #:

Warr. Date: 30 MAY 23 Work Order Date: 22 NOV 23 Inv #: 399008

WO # Job # Description JOB INFORMATION

72388 3 CUSTOMER ADVISES THAT WHEN HE HOOKS TO THE BLACK TANK FLUSHER, IT
SEEMS LIKE SOMETHING IS KINKED. A LOT OF PRESSURE BUILDS, BUT
HARDLY ANY WATER RUNS OUT OF THE DUMP VALVE.
AT FIRST, I FOUND THAT THE BLACK TANK FLUSH INLET HAD A CHECK
VALVE IN IT. I REMOVED THE VALVE FROM INSIDE THE INLET. I CHECKED
THE VACUUM BREAKER AND IT IS WORKING AS IT SHOULD. THE LINE WAS
CLEAR FROM THE INLET TO THE BREAKER. I TRIED TO BLOW AIR INTO THE
TANK FROM THE OUTPUT SIDE OF THE VACUUM BREAKER AND IT DID NOT
WANT TO LET THE AIR THROUGH THE LINE. I PUT A LITTLE MORE AIR
PRESSURE TO IT AND IT CLEARED THE BLOCKAGE. I THEN HOOKED UP ALL
THE WATER LINES AND TESTED THE SYSTEM. THE SYSTEM IS NOW WORKING
AS IT SHOULD. I THEN PUT THE INSIDE OF THE CAMPER BACK TOGETHER.

72388 4 WHEN RUNNING ON FRESH TANK, NO WATER WILL COME OUT OF ANY OF THE
FIXTURES.
I FOUND THAT THE FRESH TANK LINE COME UP OUT OF THE FLOOR AND HAD
TO TURN DOWN TO TIE INTO THE WATER PUMP LINES. I UNHOOKED THE
WATER LINES AT THE PRESSURE SIDE TO MOVE THE WATER PUMP TO A NEW
PLACE. I TURNED THE WATER PUMP SO THAT THE WATER LINE GOING TO
THE FRESH TANK DID NOT HAVE TO BE FOLDED OVER TO BE HOOKED TO THE
PUMP.

Part No Job# Description PARTS Qty Price Total

ESC06435 3 CONE WASHER SWIVEL SEAL 1.00 0.18 0.18

Claim : 72388

```
*****
Part No      Job#  Description      PARTS      Qty      Price      Total
*****
```

```
*****
Lab Code     Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990          3    MISC LABOUR CODE (EXTERNAL)      0.80     160.00     128.00
Z990          4    MISC LABOUR CODE (EXTERNAL)      0.70     160.00     112.00
```

```
Parts Total:      0.18
Labour Total:     240.00
Sublet Total:      0.00
Extras Total:      0.00
```

```
>>>> Claim Total:      240.18
```

Customer Signature: _____

Date: _____