

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
<b>BASDEN RV CENTER INC</b>		<b>CLAIM</b>	1783782
<b>DBA AMERICAN RV CENTER</b>		<b>CLAIM ORIGIN</b>	WEB
<b>600 E BASELINE ROAD</b>		<b>ORIGINAL CLAIM ID</b>	
<b>EVANSVILLE, IN 47725</b>		<b>VIN</b>	5ZT2CXHCXRL016823
<b>USA</b>		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$160.00	<b>SITE/WAREHOUSE</b>	224 / 224
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	AAPT191RBS
		<b>DEALER RO #</b>	72407
		<b>CLAIM START DATE</b>	01/08/2024
		<b>CLAIM END DATE</b>	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	30-100-02-00-001044	Drawer Guides or Tracks, pair - Interior/Cabinetry/Adjust/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2024-01-08 15:09:51 :: THE KITCHEN DRAWER HOLD BACK WAS LEFT OUT FROM THE FACTORY I INSTALLED THE 2 DRAWER HOLD BACK CLIPS THAT HAD NOT BEEN DONE AT THE FACTORY. Additional Note : bhoffman@americanrvcenter.com, 2024-01-08 15:12:53 :: 2 DRAWERS!!			
<b>Model#</b>	<b>Dir Sub Hrs</b>	0.40	<b>Sub Labor Amt</b>	\$64.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.40	<b>Appr Labor Amt</b>	\$64.00
	<b>Notes</b>			

### Labor

<b>Line# 2</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	10-9-01-00-000158	Stabilizer Jack - Bolt On, each - Frame & Chassis/Levelers, Underbelly/Replace/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2024-01-08 15:13:33 :: RIGHT REAR AND FRONT LEFT STAB JACKS ARE BENT AND INOP I FOUND THAT THE FRONT LEFT JACK WOULD NOT GO DOWN AND THE REAR RIGHT JACK HAD A BENT SCREW. I ORDERED 2 NEW JACKS AND INSTALLED THEM WHEN THEY SHOWED UP.			
<b>Model#</b>	<b>Dir Sub Hrs</b>	1.00	<b>Sub Labor Amt</b>	\$160.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.40	<b>Appr Labor Amt</b>	\$64.00
	<b>Notes</b>			
	what caused the screw to bend Dont know just started the pdi and found it was bent GOODWILL NO VCB			

<b>Submitted</b>	<b>Labor Amt</b>	\$224.00	<b>Approved</b>	<b>Labor Amt</b>	\$128.00
	<b>Parts &amp; Freight</b>	\$0.00		<b>Parts &amp; Freight</b>	\$0.00
	<b>Total</b>	\$224.00		<b>Total</b>	\$128.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE

All repairs described have been inspected and are satisfactory.