



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72457



Customer #: 54227
BRYAN, JAMES



CUSTOMER WORK ORDER

WO #: 72457 (Appointment Date: 01 DEC 2023 - Time: 09:00am)

Customer: 54227 - BRYAN, JAMES -
Tag: PH - LIGHT ORDERED. 12-1-23
Author: PH
Location: 1207 BH TO FINISH
WARRANTY

Stock #:
Stock Desc: 2022 FOREST RIVER WOLF
PUP 16BHS
Chassis #:
Serial #: 5ZT2CKEC0NY023798
Mileage:
Licence:

Invoice #: 399304
Date In: 01 DEC 23
Promised:
Date Sched:
Completed: 06 DEC 23
Warr. Date:

Job #1 - External

COMPLAINT: BACK UP CAMERA NOT WORKING, USES PHONE AND WILL NOT CONNECT.
VERIFIED THAT HE HAD HIS LIGHTS ON.

CAUSE: camera

CORRECTION: hooked up box and turned on lights and hooked phone to camper and then hooked camera
to phone took picture camera works.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Subtotal for Job #1:			0.00

Job #2 - Warranty

COMPLAINT: BACK OUTSIDE LIGHT BY STORAGE DOOR NOT WORKING. HAS SWITCH INSIDE
AND AT LIGHT.

CAUSE: outside light

CORRECTION: checked light and tested for power and it has power and ground, light barley lights up ,light
is bad.filled out sheet to get new light.ht in brought in camper and took off old light and wires,hooked up
wires to new light and tested,all good,installed light and lens and siliconed around top of light.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
F100214327	LIGHT, PORCH LIGHT AT UTILITY CENTER	1.00	4.06	4.06

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-PORCH LIGHT	1.00	17.27	17.27

Subtotal for Job #2: 53.33

Job #3 - External

COMPLAINT: UNIT HAS A SCRATCH IN THE FRONT CUSTOMER WANTS TO KNOW WHAT IT
WOULD TAKE TO GET IT BUFFED OUT

CORRECTION: SCRATCH CANNOT BE BUFFED OUT OF THAT TYPE OF MATERIAL



**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #3:				0.00

Job #4 - External

COMPLAINT: STORAGE DOOR LOCK ON DOOR SIDE NOT WORKING PROPERLY, HARD TO TURN

CAUSE: storage lock

CORRECTION: used key to lock and unlock door and thumb latch, didnt have any problems, i did go ahead and lube latch, customer might need new 751 keys.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Subtotal for Job #4:			0.00

Job #WINTER - External

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: winterize

CORRECTION: winterized unit and did everything on sheet.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Parts Total: 4.06

Labour Total: 32.00

Sublet Total: 0.00

Extras Total: 17.27

WORK ORDER TOTAL: 53.33

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 Dec 2023

