



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 72513

### CUSTOMER WORK ORDER

WO #: 72513

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: PH  
Location: 1232 BACKUP

Stock #: 11302  
Stock Desc: 2024 TT KEYSTONE  
SPRINGDALE 310BR  
Chassis #: 4YDTSGR26R7101839  
Serial #: 4YDTSGR26R7101839  
Mileage: 0  
Licence:

Invoice #:  
Date In: 08 DEC 23  
Promised:  
Date Sched:  
Completed: 19 DEC 23  
Warr. Date:

#### Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Tested appliances electrical system water and plumbing system, holding tanks,torqued lugs and checked tire pressure. Filled lp tanks. Ran lp drop test. Installed battery box. Documented model and serial numbers.checked doors drawers and cabinets.

CORRECTION: .

#### Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

#### Parts

Part #	Description	Qty	Price	Total
19-2002	55372 BATTERY BOX LARGE	1.00	N/C	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

**Subtotal for Job #PDINTT: 0.00**

#### Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*

UNITS WITH WASHING MACHINE OR ICEMAKER  
WILL BE EXTRA

\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*

NUMBER OF GALLONS USED \_\_\_\_\_

CAUSE: Ran a.f through all lines and fixtures. Drained tanks. Bypassed water heater.

CORRECTION: .

#### Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	ZMS	N/C
Z990	WINTERIZE UNIT	ZMS	N/C
Z990	WINTERIZE UNIT	ZMS	N/C

#### Parts



Customer #: 1000  
BASDEN'S AMERICAN RV,



W/O: 72513

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

**Subtotal for Job #WINTER: 0.00**

**Job #1 - Warranty**

COMPLAINT: BLACK TANK GATE VALVE SEAL IS BOUND UP

CAUSE: The gate valve won't shut. the gasket is pinched between the flange and excess pipe sealer. Removed valve. Removed sealer. Installed new gasket on valve.

CORRECTION: .

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	80.00

**Parts**

Part #	Description	Qty	Price	Total
11-0586	BLADDEX VALVE SEALS, 3IN WITH HARDWARE, 2 PER CARD	1.00	5.46	5.46

**Subtotal for Job #1: 85.46**

Parts Total: 5.46  
Labour Total: 80.00  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 85.46**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 27 Dec 2023



Customer #: 1000  
BASDEN'S AMERICAN RV,

