

BASDEN RV CENTER, INC dba AMERICAN RV  
 600 E. Baseline Rd.  
 Evansville, IN  
 US  
 47725  
 812-867-5200

WARRANTY CLAIM # 72568  
 MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC  
 Customer: 54233 - BRITTNEY N. PAKEBUSCH  
 Address: 3591 STATE HIGHWAY 97 E GONZALES, TX

78629

Phone: 830-857-0858

Stock Number: 11177 - 2024 PARADIGM 382RK 7M5FP4225RB203619

VIN: 7M5FP4225RB203619 HIN: SER#: 7M5FP4225RB203619

Mileage: 0 Work Order Comp: 28 DEC 23

Auth. No: Dealer #:

Warr. Date: 30 NOV 23 Work Order Date: 19 DEC 23 Inv #: 399669

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
72568	1	DONNIE TO GO TO MILES LANDING SPOT 10 TO FIX WATER LEAK IN SHOWER water leak	
		went to camp ground and looked for water leak turned on water and looked in basement and water came down and hit me in the face, went inside and took out shower faucet and found hot side leaking, unscrewed nut and found cone washer was ripped causing it to leak, had someone bring me a cone washer, took out old one and installed new cone washer, screwed back on and tightened, turned water on and no leaks, put back together and resiliconed faucet, went underneath to check for leaks and we are good.	

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
ESC06435	1	CONE WASHER SWIVEL SEAL		3.00	0.99	2.97

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.30	160.00	48.00

Parts Total:	2.97
Labour Total:	48.00
Sublet Total:	0.00
Extras Total:	0.00

>>>> Claim Total: 50.97

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_