



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72570

CUSTOMER WORK ORDER

WO #: 72570

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0105 CHECK PREAUTH

Stock #: 11307
Stock Desc: 2024 TT COACHMEN
CATALINA 243RBSLE
Chassis #: 5ZT2CANB1RU042729
Serial #: 5ZT2CANB1RU042729
Mileage: 0
Licence:

Invoice #:
Date In: 19 DEC 23
Promised:
Date Sched:
Completed: 28 DEC 23
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: pdi

CORRECTION: did pdi and everything on sheet,checked lp system,electrical,water and appliances.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: winterize

CORRECTION: winterized unit and did everything on sheet.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



Customer #: 1000
BASDEN'S AMERICAN RV,



24181 -50 RV ANTI-FREEZE GALLON 2.00 N/C N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: THE INDOOR AND OUTDOOR SPEAKERS ARE HOOKED UP BACKWARDS. THERE IS ONE OUTDOOR SPEAKER THAT'S ON THE SAME CIRCUIT AS THE INSIDE SPEAKER. THE OTHER INSIDE SPEAKER IS ON THE SAME CIRCUIT AS THE OTHER OUTDOOR SPEAKER.

CAUSE: speakers insise and outside

CORRECTION: checked wires on back of radio and wires were hooked up wrong,when a side was on one speaker inside and outside played together,same on b side the other speakers would work,a side should be inside and b side should be outside,rewired speakers to work properly.all good now.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	32.00

Subtotal for Job #1: 32.00

Job #2 - Warranty

COMPLAINT: THE TOILET VALVE IS LEAKING WATER

CAUSE: toilet valve

CORRECTION: seen water was behind toilet,found water leaking when flushing,moved clamp straight and tightened up and tested ,no leaks.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	80.00

Subtotal for Job #2: 80.00

Parts Total: 0.00

Labour Total: 112.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 112.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 04 Jan 2024

W/O: 72570



Customer #: 1000
BASDEN'S AMERICAN RV,

