



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 72634  
Promised Date:  
24 JAN 24

## CUSTOMER WORK ORDER

WO #: 72634

Customer: 18834 - EGLI, MARK J. -  
812-682-2594

Tag:

Author: BH

Location: 0110 BH TO CLOSE

Stock #: 10676

Stock Desc: 2022 TT COACHMEN  
CATALINA 243RBSLE

Chassis #: 5ZT2CANB2NU039607

Serial #: 5ZT2CANB2NU039607

Mileage:

Licence:

Invoice #:

Date In: 04 JAN 24

Promised: 31 JAN 24

Date Sched:

Completed: 10 JAN 24

Warr. Date: 29 APR 22

### Job #1 - Warranty

COMPLAINT: WALL PANEL IS COMING LOOSE IN SLIDE ROOM CEILING BY REAR WINDOW / IN  
BEDROOM LOOKING AT THE LIGHT SWITCH / IN BEDROOM OFF DOOR SIDE BOTTOM RIGHT  
WINDOW /

CAUSE: Walls

CORRECTION: Remove door frame in bedroom. Remove switch and receptacle. Remove wall boards. Cut  
and install new wall boards. Put switch back and receptacle. Put frame back. Remove window. Remove  
wallboard. Put studs where needed. Cut install new wallboards. Install new baton strips. Putty holes.

### Labor

| Code | Description                 | Mechanic | Total  |
|------|-----------------------------|----------|--------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB       | 0.00   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB       | 640.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB       | 640.00 |

Subtotal for Job #1: 1,280.00

### Job #2 - Internal

COMPLAINT: THE GAKSET ON THE ENTRY DOOR IS COMING OFF

CAUSE: Seal

CORRECTION: Cleaned off glue and primed. Stuck back

### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB       | N/C   |

Subtotal for Job #2: 0.00

Parts Total: 0.00  
Labour Total: 1,280.00  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 1,280.00**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited  
to work performed. Consequential damages are not covered. All guaranteed work  
must be completed in our service department.

Printed On: 1/10/2024 1:34:38PM

© 2024 Integrated Dealer Systems



Page 1 of 2

Customer #: 18834  
EGLI, MARK J.