

BASDEN RV CENTER, INC dba AMERICAN RV
 600 E. Baseline Rd.
 Evansville, IN
 US
 47725
 812-867-5200

WARRANTY CLAIM # 72638
 MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
 Customer: 1000 - BASDEN'S AMERICAN RV
 Address: 600 E. BASELINE RD. EVANSVILLE, IN
 USA
 47725

Phone:

Stock Number: 11311 - 2024 CATALINA 263BHCKLE 5ZT2CARBXR030510
 VIN: 5ZT2CARBXR030510 HIN: SER#: 5ZT2CARBXR030510
 Mileage: 0 Work Order Comp: 09 JAN 24
 Auth. No: Dealer #:
 Warr. Date: Work Order Date: 04 JAN 24 Inv #: 399963

 WO # Job # Description JOB INFORMATION

72638 1 THE BEDROOM DOOR WILL NOT LATCH CLOSED
 BEDROOM DOOR WILL NOT LATCH CLOSED
 Factory mounting of latch plate is too low. Removed latch plate
 from door frame. Cleared out material behind latch plate.
 Remounted latch plate higher on door frame. Door now latches
 closed.

72638 2 THE ARE NO TV CHANNELS AT ANY LOCATION
 There are no TV channels at any location
 Ran antenna scan. No channels found at any location. Removed TV
 booster from wall checked all cable locations. BedroomTV coax was
 in correct location on booster. Antenna and outside TV were
 switched. Put cables on correct locations on booster. Ran antenna
 scan again. Removed TV Antenna from it's base on roof. Removed
 coax cablefrom antenna. Found that center coax had insulation
 covering it. Cut off cable connector and installed new coax
 connector. Ran channel scan again. This time channels were
 found. Remounted antenna to base mount. Remounted booster to
 wall.

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00

Parts Total: 0.00
 Labour Total: 64.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 64.00

Customer Signature: _____

Date: _____