

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 72666
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 47583 - AMANDA MATHIS
Address: 2020 THEATER DR EVANSVILLE, IN

47715

Phone: 812-319-5088

Stock Number: 10966 - 2023 COUGAR HALF-TON 25RDS 4YDTCGM26PL500534

VIN: 4YDTCGM26PL500534 HIN: SER#: 4YDTCGM26PL500534

Mileage: 0

Work Order Comp: 25 JAN 24

Auth. No:

Dealer #: 1194

Warr. Date: 07 JUL 23

Work Order Date: 08 JAN 24

Inv #: 400313

WO # Job # Description JOB INFORMATION

72666 6 THERE IS A SEAL ON THE OFF DOOR SIDE FRONT NEAR THE GUTTER THAT
 SEEMS TO BE TOO SHORT. CUSTOMER WILL SHOW DETAILS AT DROP OFF.
 SCREW COVER HAS GOT SMALLER
 INSTALLED NEW SCREW COVER ON GUTTER RAIL.

72666 7 TRIM ON BATHROOM DOOR TOP CORNERS IS NOT CUT SQUARE ON INSIDE AND
 OUTSIDE OF DOOR
 Plastic c channel Trim molding is damaged and needs replaced.

72666 8 CABINET TO THE RIGHT OF THE FRIDGE LAMINATE IS PEELING OFF ON THE
 INSIDE.
 The facia for the slide room needs to be replaced. Because it's
 been wet and I's coming apart. The frame around the refrigerator
 cabinet. The bottom is swollen and the covering is coming off the
 wood

72666 1 THE BLACK TANK FLUSH WILL NOT TAKE WATER IN
 .the check valve was plumbed backwards.
 Plumbed correctly had to run air through lines to find which
 one was from the inlet.

72666 9 LAMINATE IS PEELING OFF ON CABINETRY AROUND THE TV

72666 10 REAR AWNING ARM WILL NOT STAY AFTER HE PULLS IT DOWN TO PITCH IT,
 IT RAISES BACK UP
 TIGHTENED DOWN THE BOLT ON THE PULL DOWN FOR THE AWNING ARM.

Claim : 72666

 WO # Job # Description JOB INFORMATION

72666 12 SCREWS ARE STRIPPED ON BREAKER PANEL
 Screws pulled out of wood
 Installed longer screws

 Part No Job# Description PARTS Qty Price Total

 RVDE369 6 E369 BLACK HD 1" x 25' INSERT TRI 1.00 8.53 8.53
 663531 7 Trim - Fascia - Leg - 5/8" x 6" x 1.00 20.95 20.95
 682805 7 Trim - Fascia - Insert - 5" x 84" 1.00 20.93 20.93
 663549 7 Trim - U-Channel - 2 7/8" x 8' - 3.00 4.92 14.76
 658165 8 Stile - Radius - 18mm x 2" x 108" 2.00 12.55 25.10
 658174 8 Stile - Square - 18mm x 4" x 96" 4.00 15.88 63.52

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 6 MISCELLANEOUS REPAIR 0.20 160.00 32.00
 Z990 6 MISCELLANEOUS REPAIR 0.00 160.00 0.00
 Z990 7 MISCELLANEOUS REPAIR 0.40 160.00 64.00
 Z990 7 MISCELLANEOUS REPAIR 0.00 160.00 0.00
 Z990 8 MISCELLANEOUS REPAIR 0.00 160.00 0.00
 Z990 1 MISCELLANEOUS REPAIR 0.50 160.00 80.00
 Z990 9 MISCELLANEOUS REPAIR 0.00 160.00 0.00
 Z990 9 MISCELLANEOUS REPAIR 0.40 160.00 64.00
 Z990 10 MISCELLANEOUS REPAIR 0.20 160.00 32.00
 Z990 12 MISCELLANEOUS REPAIR 0.20 160.00 32.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 8 FREIGHT - 8 1.00 117.65 117.65

Parts Total: 153.79
 Labour Total: 304.00
 Sublet Total: 0.00
 Extras Total: 117.65

>>>> Claim Total: 575.44

Customer Signature: _____

Date: _____