



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72680
Promised Date:
24 JAN 24



CUSTOMER WORK ORDER

WO #: 72680

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0129 BH TO CLOSE

Stock #: 11294
Stock Desc: 2024 TT COACHMEN
FREEDOM EXPRESS 298FDS
Chassis #: 5ZT2FEVB9RW028659
Serial #: 5ZT2FEVB9RW028659
Mileage: 0
Licence:

Invoice #:
Date In: 10 JAN 24
Promised: 31 JAN 24
Date Sched:
Completed: 29 JAN 24
Warr. Date:

Job #1 - Warranty

COMPLAINT: OUTSIDE KITCHEN WOOD RIGHT SIDE DAMAGED

CAUSE: OUTSIDE KITCHEN WOOD RIGHT SIDE DAMAGED
Cabinet wood was damaged

CORRECTION: Wood has been mounted with screws with heads countersunk. Then screw heads were covered with matching putty. See if matching tape can be ordered to cover wood strip.
Received the replacement sticky paper. Cut a piece to size then set in place. Pilled the sticky back and pressed the paper along the cabinet wood. Trimmed with silicone.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | SAR | 0.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DKM | 27.20 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DKM | 52.80 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | SAR | 0.00 |

Parts

| Part # | Description | Qty | Price | Total |
|------------|---------------------------|-------|-------|-------|
| F100392521 | 6" FREEDOM SILK SEAM TAPE | 10.00 | 0.90 | 9.00 |

Other Services

| Code | Description | Qty | Price | Total |
|------|---------------|------|-------|-------|
| FRT | UPS-SEAM TAPE | 1.00 | 17.27 | 17.27 |

Subtotal for Job #1: 106.27

Job #2 - Warranty

COMPLAINT: BATH TO BED DOOR TRIM RIGHT SIDE IS COMING OFF

CAUSE: BATH TO BED DOOR TRIM RIGHT SIDE IS COMING OFF

CORRECTION: Trim is too long and bowed out. Brad nails that secures trim to wall have pulled thru trim. Made all old brad nails flush. Shortened trim at bottom and reattached to wall. Filled all nail holes with matching putty.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DKM | 32.00 |

Subtotal for Job #2: 32.00

Job #3 - Warranty

COMPLAINT: WALL PAPER IN BATHROOM WHERE THE WASHER GOES THE WALL IS DAMAGED
SEE BEN IF YOU CANT FIND IT



Customer #: 1000
BASDEN'S AMERICAN RV,



CAUSE: WALL PAPER IN BATHROOM WHERE THE WASHER GOES, THE WALL IS DAMAGED. SEE BEN IF YOU CAN'T FIND IT.

CORRECTION: Wall paper was torn in one spot. Straightened paper and reattached.

| Labor | | | |
|-----------------------------|-----------------------------|----------|--------------|
| Code | Description | Mechanic | Total |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DKM | 0.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DKM | 32.00 |
| Subtotal for Job #3: | | | 32.00 |

Job #4 - Warranty

COMPLAINT: TRIM LOOSE IN CABINET WHERE THE WASHER GOES

CAUSE: LOOSE TRIM IN CABINET WHERE WASHER GOES

CORRECTION: Reattached vertical trim washer area with brad nails. Filled all nail holes with matching putty.

| Labor | | | |
|-----------------------------|-----------------------------|----------|--------------|
| Code | Description | Mechanic | Total |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DKM | 32.00 |
| Subtotal for Job #4: | | | 32.00 |

| | |
|--------------------------|---------------|
| Parts Total: | 9.00 |
| Labour Total: | 176.00 |
| Sublet Total: | 0.00 |
| Extras Total: | 17.27 |
| WORK ORDER TOTAL: | 202.27 |

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 29 Jan 2024

W/O: 72680
Promised Date: 31 JAN 24



Customer #: 1000
BASDEN'S AMERICAN RV,

