

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1826520
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAUB6PX029262
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT293TQBCKLE
JAMES J ZINK		DEALER RO #	72869
222 W 20TH ST		CLAIM START DATE	02/21/2024
Huntingburg, IN 47542		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	02/20/2024	WARRANTY EXPIRATION DATE	02/20/2025

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description	
	20-49-19-00-000588	Front Moldings, each - Exterior/Front, Fiberglass Cap, Cab Over/Reseal/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2024-02-21 16:54:22 :: PASSENGER FRONT CAP SEALER IS CRACKED OPEN, NEEDS RESEALED sealer cracked taped off front cap top to bottom and resiliconed with black silicone.		
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$34.00
	Notes		

Labor

Line# 2	Operation Code	Operational Description	
	60-136-01-00-001480	City Water Connection - Plumbing/Fresh Water Supply/Replace/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2024-02-21 16:55:52 :: CITY HOOK UP LEAKING city hook up city hook up was shooting water out of it, tried to push in plunger to quit leaking and seal put it was still leaking, took out screws and unscrewed water line, got new one screwed hose on it put putty on back and screwed in place. tested all good, also sealed up with silicone.		
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$51.00
Serial#	Appr Hrs	0.30	Appr Labor Amt \$51.00
	Notes		

Submitted	Labor Amt	\$85.00	Approved	Labor Amt	\$85.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$85.00		Total	\$85.00

DEALER _____ DATE _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE

All repairs described have been inspected and are satisfactory.