

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 72896
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 32260 - JENNIFER D. ELLIOTT
Address: 1620 CR 600 N FAIRFIELD, IL

62837

Phone:

Stock Number: 11143 - 2023 COUGAR HALF-TON 30BHS 4YDTCGP21PV502207

VIN: 4YDTCGP21PV502207 HIN:

SER#: 4YDTCGP21PV502207

Mileage: 0

Work Order Comp: 29 FEB 24

Auth. No:

Dealer #: 1194

Warr. Date: 17 FEB 24

Work Order Date: 19 FEB 24

Inv #: 401704

WO # Job # Description JOB INFORMATION

72896 3 BLACK TANK FLUSH DON'T WORK

black tank flush

tested black tank flush and no water to tank, checked under sink and tracked water lines and found vacuum breaker was hooked up backwards, had to cut both lines and change fittings so it would work, tested flow through vacuum breaker and it was working right, when i hooked up other side it was not getting to tank, cut underbelly in several places and found white water line was kinked in half and leaking, pulled line through floor and cut out kink, then spliced in line to vacuum breaker and test again, now im getting water to tank, taped up underbelly where i cut and tied up lines and vacuum breaker and put panel back in place.

Part No	Job#	Description	PARTS	Qty	Price	Total
THE94239	3	94239 VACUUM BREAKER/CHECK VALVE		1.00	19.67	19.67

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	3	MISCELLANEOUS REPAIR		0.00	160.00	0.00
Z990	3	MISCELLANEOUS REPAIR		1.50	160.00	240.00
Z990	3	MISCELLANEOUS REPAIR		0.00	160.00	0.00

Parts Total: 19.67
Labour Total: 240.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 259.67

Customer Signature: _____

Date: _____

Claim : 72896

```
*****
Lab Code  Job#  Description      LABOUR                      Hrs      Rate      Total
*****
```