

Pre-Authorization

Pre-Authorization number PA03627626		Reference no: 72896	Status: Approved	Approved by papca	Approved date 3/11/2024
Servicing Dealer	Name	Address	VIN	Retail sold on	

1194	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTCGP21PV502207	3/9/2024
------	----------------------	---	-------------------	----------

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6109414A	Holding Tank Flus	0.00	1.50	1.50		1	0.20	Complaint:BLACK TANK FLUSH DON'T WORK Cause:black tank flush Correction:tested black tank flush and no water to tank,checked under sink and tracked water lines and foundvacuum breaker was hooked up backwards,had to cut both lines and change fittings so it would work,tested flow through vacuum breaker and it was working right,when i hooked up other side it was not getting to tank,cut underbelly in several places and found white water line was kinked in half and leaking,pulled line through floor and cut out kink,then spliced in line to vacuum breaker and test again,now im getting water to tank,taped up underbelly where i cut and tied up lines and vacuum breaker and put panel back in place. KRV – Labor time adjusted allowing for proper repair procedure to be performed.

Pre-Authorization number PA03627626

1.50For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return toKeystone RV Company