

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 72928
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 54443 - JAMES D. WILLIAMS
Address: 30 S IROQUOIS DR EVANSVILLE, IN

47714

Phone:

Stock Number: 10874 - 2023 CHEROKEE 306MM 4X4TCKG20PX161435

VIN: 4X4TCKG20PX161435 HIN:

SER#: 4X4TCKG20PX161435

Mileage: 0

Work Order Comp: 29 FEB 24

Auth. No:

Dealer #:

Warr. Date: 27 FEB 24

Work Order Date: 23 FEB 24

Inv #: 401689

WO #	Job #	Description	JOB INFORMATION
72928	8	FRONT JACK DOES NOT WORK tongue jack tested tongue jack and it dosent work,or the light, tested for power and it has power, tested ground and it has good ground, tried to hook it up to battery to make sure and it dosent work, took off jack and installed new jack and wired up, all good now.	
72928	9	THE PUMP FOR THE SLIDE ROOM KEEPS KICKING OUT. pump for slideroom when i run rooms in the pump kicks out, checked tombeta and cleaned wires they were corodded, room still did it, next found breaker was kicking out on tongue of camper, added a breaker to to other breaker, because it was pulling to much, and had to make jumper wire, tested rooms again and it works fine now.	
72928	10	DECAL ON DOOR IS BAD decal on door took pictures of decal and tag, filled out sheet for decal	
72928	11	CHEROKEE DECAL ON BOTH SIDES IS COMING OFF cherokee decals took pictures and measurements on both sides and filled out sheet.	
72928	4	OUTSIDE REFRIDGERATOR HAS DENTS IN DOOR ref	

Claim : 72928

WO # Job # Description JOB INFORMATION

ref has 2 dents in outside of door, filled out sheet to get new one. CUSTOMER CAME AND INSTALLED HIM SELF

72928 5 THE REFRIGERATOR DOES NOT WORK
ref not working
checked fuse at fuse panel and it was good, next checked fuse in front of ref and it is good, took screws out of top and bottom and pulled ref out and found power wire was not plugged in, plugged in wire and it works, put ref back in place and installed screws and bottom cover.

72928 6 THE TRIM IN THE SLIDE ROOM IS COMING OFF
trim in slideroom
found trim was to long and bowed, took off trim and cut to side and stapled back in place.

72928 7 THE TRIM IN THE HALLWAY IS COMING OFF
trim in hallway
stapled trim back in place and covered nail holes.

Part No	Job#	Description	PARTS	Qty	Price	Total
SCPJET-3755	8	3500#	STROMBERG ELEC JACK -BULK	1.00	200.18	200.18
PME16-3050	9		CIRCUIT BREAKER-50A	1.00	9.19	9.19
F100220375	10		DECAL, 2021 CHEROKEE DOOR GRAPHIC	1.00	12.37	12.37
F100144937	11		DECAL, 2020-22 CHEROKEE BLACK LAB	2.00	13.48	26.96
F100411126	4		REFER, CONTOURE 1.6CU.FT W/SMALL	1.00	148.01	148.01

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	8	MISC LABOUR CODE	(EXTERNAL)	0.50	170.00	85.00
Z990	9	MISC LABOUR CODE	(EXTERNAL)	0.41	170.00	69.70
Z990	9	MISC LABOUR CODE	(EXTERNAL)	0.39	170.00	66.30
Z990	10	MISC LABOUR CODE	(EXTERNAL)	0.20	170.00	34.00
Z990	10	MISC LABOUR CODE	(EXTERNAL)	0.00	170.00	0.00
Z990	10	MISC LABOUR CODE	(EXTERNAL)	0.00	170.00	0.00
Z990	11	MISC LABOUR CODE	(EXTERNAL)	0.40	170.00	68.00
Z990	11	MISC LABOUR CODE	(EXTERNAL)	0.00	170.00	0.00
Z990	4	MISC LABOUR CODE	(EXTERNAL)	0.00	170.00	0.00
Z990	4	MISC LABOUR CODE	(EXTERNAL)	0.50	170.00	85.00
Z990	5	MISC LABOUR CODE	(EXTERNAL)	0.50	170.00	85.00
Z990	6	MISC LABOUR CODE	(EXTERNAL)	0.10	170.00	17.00
Z990	7	MISC LABOUR CODE	(EXTERNAL)	0.10	170.00	17.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	10	UPS-DECALS JOBS 10,11		1.00	17.32	17.32

Claim : 72928

Excode Job# Description EXTRAS Qty Price Total

FRT 4 SHIPPING-REFER 1.00 117.45 117.45

Parts Total: 396.71
Labour Total: 527.00
Sublet Total: 0.00
Extras Total: 134.77

>>>> Claim Total: 1,058.48

Customer Signature: _____

Date: _____