



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72969

CUSTOMER WORK ORDER

WO #: 72969

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: PH

Location: 0311 CHECK PPREAUTH

Stock #: 11341

Stock Desc: 2024 TT KEYSTONE

SPRINGDALE 260BHC

Chassis #: 4YDTSG23R7102777

Serial #: 4YDTSG23R7102777

Mileage: 0

Licence:

Invoice #:

Date In: 29 FEB 24

Promised:

Date Sched:

Completed: 09 MAR 24

Warr. Date:

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize trailer

CORRECTION: Winterize bathroom,kitchen and and holding tanks which includes shower,toilet, sink in bathroom and kitchen faucet.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JH	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #SUMMERLAND - Internal

COMPLAINT: SUMMERLAND PDI

CAUSE: Pdi

CORRECTION: Pulled trailer in the shop.

Preformed PDI.

Water system checks out good.

Plumbing wasgood,no leaks.

Electrical system checks out good.

12vdc system is good and works properly.

Lp gas system operates as it should. Preformed lock up Test passed with maintaining 11" of WC

Interior checs out good.

Lights all work.

Running gear is all good with tires aired to 75PSI.


Refrigerator is working properly

Hot water heater operates properly.

Sealed roof with Dicor self leveling sealant in sevel areas.



Customer #: 1000
BASDEN'S AMERICAN RV,





Awning works as it should

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	8.00	N/C	N/C

Subtotal for Job #SUMMERLAND: 0.00

Job #1 - Warranty

COMPLAINT: ENTRY DOOR NEED ADJUSTED

CAUSE: Entry door needs adjusted

CORRECTION: Check entry door, found screws in door frame not seated against door frame, installed screws into door frame. Also adjusted door catch, door opens and shuts properly.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	34.00

Subtotal for Job #1: 34.00

Job #2 - Internal

COMPLAINT: METAL ABOVE THE WINDOW IS ALL BOWED OUT

CAUSE: Metal above bedroom window on left side is bowed out.

CORRECTION: Metal is bowed out, metal is fastened tightly to wood and wood is tight against frame work. Nothing to repair.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	N/C

Subtotal for Job #2: 0.00

Parts Total: 0.00
Labour Total: 34.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 34.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 09 Mar 2024

