FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	**CLAIM STATUS**	Authorized
BASDEN RV CENTER INC		**CLAIM**	1854984
DBA AMERICAN RV CENTER		**CLAIM ORIGIN**	WEB
600 E BASELINE ROAD		**ORIGINAL CLAIM ID**	
EVANSVILLE, IN 47725		**VIN**	4X4TCKE26RX163793
USA		**CHASSIS VIN**	
		MILEAGE	0
Labor rate:	$170.00	**SITE/WAREHOUSE**	017 / 017A
OWNER INFORMATION		**ITEM #**	ACKT29QB
		DEALER RO #	72994
		CLAIM START DATE	03/20/2024
		CLAIM END DATE	01/01/1900
Retail Date of Purchase		**WARRANTY EXPIRATION DATE**	

Claim Line Details

Labor

Line# 1

Operation Code
30-98-24-00-002295

Operational Description
Bed or Bunk Structure - Interior/Beds, Mattress/Repair/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-03-20 09:31:03 :: REAR BED PLATFORM HITTING THE WALL - NOTED ON DELIVERY. REAR BED PLATFORM HITTING WALL (NOTED ON DELIVERY). Rear bed platform rubs wall when lifting to get to under bed storage. Removed mattress from bed. Removed screws from hinges. moved platform away from to get clearance. Remounted hinges. Checked operation of platform lift. Not hitting wall now.

Model#		**Dlr Sub Hrs**	0.30	**Sub Labor Amt**	$51.00
Serial#		**Appr Hrs**	0.30	**Appr Labor Amt**	$51.00

Notes
Pictures are required for this repair. Please provide the following pictures:
1. The complete item (all sides, part removed)
2. The defect, if possible
3. Identifying marks, tags, labels, stamps - or location - or model/serial numbers
Please use JPEG or PDF formats only when attaching pictures to your claim.

Forest River requires a prior authorization (PAR) for this repair. The Forest River Warranty Representative will review the requested repair. Please be sure to read the Notes & Feedback on the repair line for authorization details.

photos added
repaired

Submitted			**Approved**		
	Labor Amt	$51.00		Labor Amt	$51.00
	Parts & Freight	$0.00		Parts & Freight	$0.00
	Total	$51.00		Total	$51.00

DEALER SIGNATURE **DATE**
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER SIGNATURE **DATE**
All repairs described have been inspected and are satisfactory.